



Summary Building Condition Survey Report

Of

**Cluny Primary School
South Pringle Street, Buckie AB56 1PX**

25th and 26th April 2022



Z01032 / ADC & NS

CONTENTS

01 – Introduction

02 – Property Description and Methodology

03 – Summary of Condition / Key Issues

04 – Conclusion

Appendices:

A – Limitations and Exclusions

B – Photographic Schedule

1. Introduction

- 1.1. This report has been prepared by Andrew Clark MRICS, MCIOB and Neal Stewart Building Services Engineer, of Moray Council. The report is confidential to Moray Council and is not intended for public release without Moray Council's express approval. The report summarises the condition of the property condition at the time of the survey, periodic reviews of material condition will be required. An inspection of the property was undertaken on Monday and Tuesday, 25th and 26th April 2022, a further survey was carried out of the high level flat roof on Thursday 12th May 2022.
- 1.2. The report seeks to provide a brief summary of the condition of repair, identifying the principal defects and wants of repair, together with the main points of concern arising from the inspection. Items of a routine or minor maintenance nature have generally not been listed.
- 1.3. At the time of our inspection, the weather conditions were cool, cloudy with showers.
- 1.4. The premises comprise a Primary School with a separate Dining Hall. The school is constructed in single and 2 storeys, with the Dining Hall being single storey.
- 1.5. The property was occupied during our inspection which was thus limited by the nature and extent of fixtures and fittings and of decorative finishes. In particular, the existence of fitted floor finishings throughout limited any inspection of the underlying floor structure. Framing out of walls and plasterboard linings conceal the underlying structure and it is possible that defects relating to moisture ingress may exist which are not revealed internally. Please also note and consider the Limitations and Exclusions Section, which is appended to this report.
- 1.6. Pitched roofs were examined from ground level with the use of binoculars. Accessible flat roofs were examined from a standard 3.80m ladder, the flat roof above the first floor corridor was examined with the use of a mobile elevated platform. Access was provided to all internal areas with the exception of the Gym Hall roof space which was not accessible due to the height of the ceiling.
- 1.7. All mechanical and electrical building services were inspected as far as reasonably practical. Domestic water supply pipework, heating pipework, alarm systems cabling and small power systems cabling was in most cases concealed in internal walls or under floor spaces and not reasonably practical to inspect. An effort has been made to assess the age and likely condition of these elements by using historic data, where available, to pinpoint the likely age of materials.
- 1.8. Extract and supply fan ventilation systems were tested by switching on and observing operation only. A detailed inspection of fan units, ductwork or controls has not been carried out during the non-intrusive survey.
- 1.9. Fire and intruder alarm systems were visually inspected for condition and age as far as reasonably practical and no physical testing was carried out on these services during the survey.

2. Property Description and Methodology

- 2.1 The property comprises of a single and two storey building with a separate single storey building both having pitched and flat roofs.
- 2.2 The subjects are of brick construction. Roofs are covered with natural slate to pitched roofs and mineral felt to flat roofs, rainwater goods are a combination of cast iron and upvc ogee gutters, upvc half round gutters and cast iron downpipes. There is a timber framed tower to the centre of the main roof with copper capping. External walls are of natural stone with render and roughcast panels, the Dining Hall has a wet dash roughcast finish to all walls. Floors are a combination of concrete slab, suspended concrete and suspended timber. Stairs are constructed in concrete with additional steel support. Windows are aluminium top hung, with double glazed units. External doors are generally solid core timber, with an aluminium door and screen to the main entrance.

Internally, ceilings are painted plaster, plasterboard and suspended ceiling tiles, walls are painted render, plasterboard, fibreboard, wet wall and ceramic tiles. Floor coverings comprise carpet, carpet tiles, sheet vinyl and vinyl tiles. Internal doors comprise timber solid core doors with glazed panels and timber hollow core doors. Sanitary ware comprises individual urinals, close coupled WC's and vanity basins in pupil toilets and WC's and wall hung basins in staff toilets, classrooms have stainless steel sinks set in base units.

The heating system for the main school comprises 3 natural gas boilers, steel pipework, steel radiators with BMS control system, all recently installed in 2017/2018. Automatic safety systems exist to protect against various faults.

The dining block has an independent natural gas boiler, steel pipework, radiator and BMS control system recently installed in 2019/2020. Automatic safety systems exist to protect against various faults.

Domestic hot water in the main school block is pumped via an indirect storage calorifier located in the basement. Electric immersion heater back up is available to the main gas boiler heat source. Recently fully upgraded in 2017/2018.

Hot water in the dining block is pumped via a pressurised hot water storage calorifier and twin electric immersion heaters are available to back up the gas boiler heat source if required. Recently fully upgraded in 2019/2020.

Cold water in the main school is both mains fed directly and via a cold water storage tank located in the attic space. New pipework and insulation has been recently installed in 2017/2018 as part of upgrade works.

Cold water in the dining room is piped directly from the mains supply with no storage tanks. New pipework and insulation has been recently installed in 2019/2020 as part of upgrade scope.

Mechanical ventilation is provided by a number of electrical extract fans located in various rooms around the main school block.

Mechanical extract ventilation in the kitchen block only exists within the main kitchen and is provided by 4 window mounted direction reversible, speed controllable fans.

An air conditioning unit, with outdoor refrigerant loop unit also serves the main kitchen for cooling purposes.

The electrical installation in the main school has recently been replaced and upgraded in 2017/2018, with new sub mains cabling, distribution boards, general wiring and accessories all being installed as part of this upgrade scope.

The electrical installation in the kitchen block has also recently been replaced and upgraded in 2019/2020 with new sub mains cabling, distribution boards, general wiring and accessories all being installed as part of this upgrade.

The lighting system in the main school comprises various types of surface mounted and recessed LED fittings with PIR energy saving controls installed. Lighting and controls were upgraded in the main school in 2017/2018.

The lighting system in the main school comprises various types of surface mounted and recessed LED fittings with PIR energy saving controls installed. Lighting was upgraded in the kitchen block in 2017/2018.

External and emergency lighting is throughout both buildings and was installed/replaced as part of upgrade works.

The main school building has a modern, addressable panel, smoke detection and alarm system installed throughout. This was recently installed as part of electrical upgrade works in 2017/2018.

The kitchen block building has a modern smoke detection, addressable panel and alarm system installed throughout. This was recently installed as part of electrical upgrade works in 2019/2020.

The main school block has a modern intruder alarm system installed throughout, with sensors throughout ground and 1st floors. This system was recently installed as part of electrical upgrade works in 2017/2018.

The kitchen block has a modern intruder alarm system installed throughout, with sensors throughout. This system was recently installed as part of electrical upgrade works in 2019/2020.

The main school has an extensive CCTV installed comprising 11 external and 1 internal field cameras. Viewing monitors and recording equipment are available in the janitors and reception offices. This system was recently installed as part of electrical upgrade works in 2017/2018.

The main school has a security door Paxton access control system installed to allow reception staff to control access to the main entrance and internal school entrance door. This was recently installed as part of electrical upgrade works in 2017/2018.

The main school internal access corridor swing doors have magnetic hold open device systems installed. These systems include interfaces connected to the fire alarm system to disable these magnetic hold open devices in the event that the fire alarm is activated.

2.3 Building size – The properties GIFA is 2355m2.

2.4 Condition codes and priority categories.

CONDITION SUMMARY MATRIX	
Good - A	Performing well and operating efficiently
Satisfactory - B	Performing adequately but showing minor deterioration
Poor - C	Showing major defects and/or not operating adequately
Bad - D	Life expired and/or serious risk of imminent failure
N/A	Not applicable for assessment

PRIORITY RATING MATRIX	
1	Must Do (immediate) to address essential H&S/comply with law/avoid service disruption.
2	Should Do (within years 1 and 2) to achieve/maintain basic standards.
3	Would Do (within years 3 to 5) desirable works if affordable.
4	Programmed (within years 6 to 25) consider within Planned Maintenance.

3. Summary of Principal Considerations

3.1 Primary School Building

- Felt roofing has exceeded its useful life.
- Flat roof outlets are small and frequently block.
- Cast iron ogee gutter leaking at the joints.
- Isolated double glazed units have failed seals and have become fogged.
- A large proportion of window ironmongery has failed or is missing.
- Timber fire escape doors have extensive rot to the bottom edge.
- Internal doors and ironmongery, damaged and have exceeded their useful life.
- Carpets are worn and heavily soiled.

3.2 Dining Hall

- Felt roofing has exceeded its useful life.
- Cast iron gutters are extensively corroded.
- External walls have significant cracking.
- Internal plastered walls cracked and spalling.

3.3 Mechanical and Electrical Installations

- The extract fan in the male staff toilets 1/23a – main school is defective.
- The extract fan in the disabled shower room 1/30 is defective.
- 3 of 4 extract fans within the main kitchen in the dining block are defective.
- Air conditioning unit serving the kitchen urgently requires cleaning and work to repair ductwork.
- The staff, boys and girls toilets in the dining block have no extract fans installed.
- The gas boiler flue which runs through the boys toilets in the dining block, should have carbon monoxide detection interlock system installed in the toilet due to the flue being concealed.
- Recently installed LED lighting in the boys toilets in the dining room is defective.
- Recently installed LED lighting in the dining room has one defective fitting.
- Dining block plant room pipework is not clearly labelled for ID purposes.
- Dining block plant room gas control valves are not clearly identified by prominent notices.
- Water pipework is not fully insulated in either block in small areas.

3.4 External Works

- Tarmacadam car park breaking up and pot holed.
- Concrete post and panel fence has exposed reinforcement and missing panels.
- Blockwork wall cracked and leaning, adjacent to trees.
- Natural stone walls have eroded and missing pointing.
- Gates have extensive corrosion.

4. Conclusion

4.1 A brief summary of the elements condition.

Element	Condition	Priority
Roofs	C	2
Floors & Stairs	C	3
Ceilings	B	4
Ext. Walls, Windows & Doors	C	3
Internal Walls & Doors	C	3
Sanitary Services	B	4
Mechanical	B	4
Electrical	A	4
Decoration	C	2
Fixed Int. Facilities	B	4
External Areas	D	1
Outdoor Sports Facilities	B	4

This information must be transferred to the Master Core Fact Sheet.

4.2 Improvements Recommended

To prevent or reduce, vandalism / damage / accelerated deterioration.

- Installation of mechanical extract fans to dining block toilets.
- Installation of purpose designed extract canopy in main kitchen to exhaust cooking fumes/steam and excess heat from island cooking appliances.
- Consideration could be given to the installation of a fixed fire-fighting or sprinkler system to improve resilience in the event of fire.
- Carry out review of inadequate car park drainage.

Appendix A

Limitations and Exclusions

Introduction

We will not seek to impose any particular limitations upon the survey work beyond those of normal surveying practice.

We will carry out a detailed, non-disruptive, visual inspection of the exposed parts of the building fabric that are readily and safely accessible at the time of our survey, using our standard survey equipment.

Our report will express our opinion on the condition and standard of construction of the inspected parts of the property and recommend further investigation or repair where necessary.

The survey will be limited to the subject property and no responsibility will be accepted for any defects that might materially affect the property, which are out with the scope of the survey.

Health and Safety

The inspection will be executed in a fashion in compliance with the Health & Safety at Work, etc Act 1974. Unless otherwise stated, it will be done without the benefit of internal or external scaffolding, guard rails or mechanical hoists. The external inspection will, therefore, be limited to ground level to inspection from accessible opening in the external fabric, or by the use of a 5 metre sectional ladder.

Deleterious Materials

Testing of components or taking of samples will not be taken through our inspection. If the presence of deleterious materials is suspected in the construction of the building, we will recommend further investigations are carried out by the appropriate specialists. Our inspection does not constitute an asbestos survey in accordance with the Control of Asbestos at Work Regulations.

Services

We will carry out a visual inspection of the primary service installations to include electrical and mechanical services where accessible. No tests of existing services will be undertaken at the time of our inspection. If, as a result of inspection and where considered necessary, we will advise if further investigations and reports should be obtained by independent specialists.

Unless agreed beforehand, our inspection will not comment on the suitability of the property for any use and the client is, therefore, advised to ensure that their use is possible and all processes, trades and activities are viable and permitted. No enquiries will be made to any local or statutory authority regarding any form of "Notice" that might have been served on the property at any time in the past or present. Similarly our report excludes any investigation into the structural design and suitability and compliance with legislation relating to buildings.

Environmental Conditions

The scope of the survey will be limited by the particular weather conditions pertaining at the time of inspection and no guarantee will be given with regard to the performance of the elements of the building during different conditions.

Where existing, the external inspections will be limited by the presence of any coverings of vegetation and no stripping off of the vegetation, including ivy, trellises, etc will be undertaken.

Contamination and Pollution

We will not make enquiries or investigations as to whether the property or any part of it or any neighbouring property appears on any register of contaminated land or might be contaminated or otherwise affected within the scope of the Environmental Protection Act 1990 or other legislation. We will, therefore, be unable to report that the property is free from risk in this respect. For the purpose of our report we will assume that such enquiries would reveal nothing which would affect the terms of our report.

Confidentiality and Use.

Our report is for the sole use of Moray Council and is confidential to the Council and their Professional Advisors. It should not be reproduced in whole or in part or relied upon by a Third Party for any purpose without the express prior written consent of Moray Council.

It should be understood that the report must not be used as any form of specification. Prior to the selection of an appropriate specification, it is likely that further investigation and exploratory works will be required following on from the survey in order to determine the full extent of the specification works necessary prior to submission to contractors for pricing.

Appendix B

Record Photographs

Roofs



1. Main school, pitched roof



2. Displaced rafter supports



3. Dining Hall roof structure



4. Slated roofs



5. Slates and lead flashings



6. Slated roof to Gym Hall



7. Dining Hall slate roof



8. Mineral felt to single storey flat roofs



9. Lichen on the surface of felt roofs



10. Vegetation and debris on flat roofs



11. Felt surface crazing



12. Felt surface cracking



13. Ponding on flat roofs



14. Dining Hall felt roof



15. Felt cracking and crazing



16. Single ply membrane to high level flat roof



17. Soiled surface of single ply membrane



18. Skylight to main school roof



19. Skylight internally



20. Insulation disturbed in main school roof



21. Insulation missing in main school roof



22. Insulation missing in Dining Hall roof



23. Steel ogee gutter to main school



24. Leaking gutter joints



25. Leaking gutter joints



26. UPVC ogee gutter to school and Gym Hall




27. UPVC ogee gutter outlets



28. 1/2 round cast iron gutter to Dining Hall



29. 1/2 round cast iron gutter to Dining Hall



30. 1/2 round UPVC gutter to Dining Hall



31. Blocked outlets to felt roofs



32. Small outlets to felt roofs



33. Damage to cast iron rainwater downpipes



34. Damage to cast iron rainwater downpipes



35. Octagonal tower to main school roof



36. Tower's timber structure

External Walls



37. Stone walls to main school



38.



39. Isolated cracking, pointing required



40. Cracking to Dining Hall walls



41. Cracking to Dining Hall walls



42. Main school, underfloor ventilation



43.



44. Render and roughcast panels



45. Isolated spalling of render panels



46. Dining Hall, repairs to roughcast



47. Main entrance



48. Timber double doors



49. Single timber doors



50. Timber wet rot



51.



52. Dining Hall timber double doors



53. Wet rot in door frames



54. Large aluminium windows



55.



56. Standard aluminium windows



57. Timber window sills



58. Defective double glazed units



59. Broken glazing



60. Defective double glazed units



61. Cracked double glazing



62. Defective/missing ironmongery



63. Missing ironmongery / sealed windows

External Decoration



64. Timber window sills



65. External timber doors



66. Cast iron rain water goods



67. Guard rails

Steps & Ramps



68. Concrete steps



69. Chipped nosings



70. Concrete stair to Boiler Room



71. Chipped nosings



72. Concrete stair to Boiler Room



73. Concrete ramps



74. Cracked concrete ramps



75. Galvanised guardrails

Floors



76. Sheet vinyl



77. Soiled sheet vinyl



78. Holes in sheet vinyl



79. Corridor carpet



80. Holes in carpet



81. Soiled and stained carpets



82. Vinyl tiles



83. Gym Hall timber flooring



84. Timber flooring repairs



85. Boiler room painted concrete floor



86. Steel and concrete staircases



87. Vinyl treads and risers



88. Vinyl taped repairs



89. Vinyl cracked



90. Vinyl lifting




91. Timber handrails and metal balustrades



92.

Ceilings



93. Suspended ceiling tiles



94. Plastered ceilings



95. Plasterboard ceilings



96. Failed taped joints

Internal Walls



97. Brick and plastered internal walls



98. Dining Hall cracked walls



99. Cracking to masonry walls



100. Damaged fibreboard linings



101. Damaged plastered walls



102.



103.



104. Damaged plasterboard walls



105. Fibreboard linings



106. Fibreboard linings damaged



107. Wetwall to Kitchen walls



108. Wetwall to Dining Room walls



109. Ceramic wall tiles above basins



110. Timber double doors to school building



111.



112. Timber classroom doors with glazing panels



113. Damaged timber doors



114.



115. Timber doors in Dining Room



116. Borrowed lights to classrooms



117. Defective ironmongery



118. Original brass ironmongery

Sanitary Ware



119. Individual urinals



120.



121. Typical WC



122. Older WC's



123. Wall hung wash hand basins



124. Vanity basins



125. Accessible toilet



126. Composite cubicle partitions



127. Vanity base units



128. Commercial kitchen



129. Classroom base units



130. Damage to base units



131. West Hall base units




132.



133. Classroom stainless steel sinks



134. Round hand washing sinks



135. PVC waste pipes

Internal Decoration



136. Peeling and flaking decoration



137.

Furniture



138. Pupil tables & chairs



139.



140. Staff room furniture

Mechanical & Electrical Installations



141. Natural gas condensing boilers. 0/1 Boilerhouse.



142. Boiler common flue external.



143. Spirovent fill and degasser unit – heating. 0/1



144. Pumps – heating system. 0/1 Boilerhouse.



145. Pipework – heating system. 0/1 Boilerhouse.



146. Radiator – typical classroom.



147. BMS control panel – heating, ventilation and electrical. 0/1 Boilerhouse.



148. Expansion vessel – heating system. 0/1 Boilerhouse.



149. Hot water storage calorifier and pipework. 0/1.



150. Pipework – hot water distribution.



151. Cold water storage tank – attic.



152. Cold water copper pipework and meter. 1/20 box.



153. Gas safety control panel – plant room 0/1.



154. Gas pipework and solenoid valve – plant room 0/1.



155. Extract fan – boys toilets 1/21.



156. Extract fan Access shower room 1-30.



157. Incoming electrical supply and fuses 1-16 cupboard.



158. Main panel distribution power board 1-16 cupboard.



159. Distribution boards. Lighting and power typical.



160. Sub mains cabling cupboard 1-22.



161. Plastic dado trunking and sockets and switches. Typical classroom.



162. Galvanised conduit and distribution general wiring. Typical.



163. Electrical containment for distribution wiring.



164. Sockets – typical classroom.



165. Lighting – typical classroom



166. Lighting – circulation spaces typical.



167. Lighting toilets and stores



168. Emergency exit lighting – typical.



169. Emergency lighting – self - contained non maintained fitting.



170. Lighting – external building walls.



171. Fire alarm control panel main entrance 1/1



172. Fire detector head and sounder - typical



173. Fire alarm break glass call point – typical.



174. Fire alarm system wiring – typical.



175. Lightning conductor cable and earth rod.



176. Lightning conductor assembly and cable – chimney stack – gym hall 1/5.



177. Period bell – corridor typical.



178. Period bell programmer – janitors room 1/2



179. Disabled toilet alarm system reset unit. Access shower room 1-30.



180. Disabled toilet alarm indicator and control unit. Reception office 1/7a.



181. Intruder alarm system keypad. Main entrance 1/1



182. Intruder alarm system PIR sensor. Typical throughout.



183. CCTV system fixed camera. Internal at reception.



184. CCTV system external fixed camera. Typical.



185. CCTV system monitor – janitors room 1/2.



186. CCTV system monitor and recorder office 1/7a



187. Security door video and audio panel. Reception 1/7b



188. Security door access system – main entrance door. Video and audio.




189. Door access control. Magnetic hold open devices complete with fire alarm interface.



190. Magnetic door hold open devices (2)

Mechanical and Electrical - Dining Block



191. Gas boiler – plant room 1-50



192. Spirovent fill and degas unit plant room 1-50



193. Boiler flue. Boxed in through boys toilets 1/52.



194. Pipework – heating system in attic. Dining block.



195. Hot water storage calorifier – plant room 1/50



196. BMS control panel. Mechanical and electrical. 1/50 Plant room.



197. Cold water copper pipework – boys toilets 1/52.



198. Radiator – typical dining hall.



199. Gas safety control panel. Plant room 1/50.



200. Gas pipework – copper distribution plant room 1/50



201. Extract fan – kitchen windows. 1-42



202. Air conditioning unit – indoor. Serves kitchen 1/42.



203. Air conditioning outdoor unit. Serves kitchen 1/42



204. Incoming power supply 1/40 kitchen cupboard.



205. Distribution boards – power. 1/40 kitchen cupboard.



206. Main switch and distribution board – power. 1/40.



207. Lighting – dining block corridor. Typical 1/53



208. Lighting – dining block girls toilets. 1/51



209. Emergency lighting dining block. Typical




210. External lighting – dining block.



211. Fire alarm panel. Dining block.



212. Fire detection head dining block typical.



213. Fire alarm break glass point. Dining block.



214. Period bell programmer – dining block.



215. Steam oven extract canopy. Main kitchen.



216. Steam oven extract canopy baffles. Detail.



217. Intruder alarm panel 1/47 dining block.



218. Intruder alarm sensor – dining block typical.

External Works



219. Tarmacadam car park



220. Surface breaking up and potholed



221. Tarmacadam playground



222. Main playground



223. Playground furniture



224.



225. Concrete post and panel fence



226. Exposed, corroding reinforcement



227. Timber fence and gate



228. Metal railing fence



229. High, close boarded fence



230. Metal tubular gates



231. Corrosion of tubular gates



232, Side gate – corrosion and damage



233. Block walls bunging next to trees



234. Damage to blockwork walls



235. High blockwork wall



236. Natural stone wall



237. Repointing of stone walls required



238. School signage



239. Surface water gullies



240.



241. Car park gully



242. Back inlet gullies, partially blocked



243. Bike shelter



244. Corrosion of the steel frame



245. Damage to the profile cladding



246. Landscaping – grass and trees



247. Games stands



248.