

Summary Building Condition Survey Report

of

**Portgordon Primary School
Richmond Terrace, Portgordon AB56 5RA**

13th September 2022



Z00447 / ADC & NS

CONTENTS

01 – Introduction

02 – Property Description and Methodology

03 – Summary of Condition / Key Issues

04 – Conclusion

Appendices:

A – Limitations and Exclusions

B – Photographic Schedule

1. Introduction

- 1.1. This report has been prepared by Andrew Clark MRICS, MCIOB and Neal Stewart Building Services Engineer, of Moray Council. The report is confidential to Moray Council and is not intended for public release without Moray Council's express approval. The report summarises the condition of the property condition at the time of the survey, periodic reviews of material condition will be required. An inspection of the property was undertaken on Tuesday 13th September 2022.
- 1.2. The report seeks to provide a brief summary of the condition of repair, identifying the principal defects and wants of repair, together with the main points of concern arising from the inspection. Items of a routine or minor maintenance nature have generally not been listed.
- 1.3. At the time of our inspection, the weather conditions were dry, mild and windy.
- 1.4. The premises comprise a primary school constructed in a single storey. The school was constructed circa 1890 with further extensions circa 1930.
- 1.5. The property was occupied during our inspection which was thus limited by the nature and extent of fixtures and fittings and of decorative finishes. In particular, the existence of fitted floor finishings throughout limited any inspection of the underlying floor structure. Framing out of walls and plasterboard linings conceal the underlying structure and it is possible that defects relating to moisture ingress may exist which are not revealed internally. Please also note and consider the Limitations and Exclusions Section, which is appended to this report.
- 1.6. Pitched roofs were examined from ground level with the use of binoculars. Accessible flat roofs were examined from a standard 3.80m ladder, the flat roofs above Room 3 (1/39) was not accessible due to the height of the parapet wall. Access was provided to all internal areas with the exception of the roof spaces above the central and northern pitches.
- 1.7. All mechanical and electrical building services were inspected as far as reasonably practical. Domestic water supply pipework, heating pipework, alarm systems cabling and small power systems cabling was in most cases concealed in internal walls or under floor spaces and not reasonably practical to inspect. An effort has been made to assess the age and likely condition of these elements by using historic data, where available, to pinpoint the likely age of materials.
- 1.8. Extract and supply fan ventilation systems were tested by switching on and observing operation only. A detailed inspection of fan units, ductwork or controls has not been carried out during the non-intrusive survey.
- 1.9. Fire and intruder alarm systems were visually inspected for condition and age as far as reasonably practical and no physical testing was carried out on these services during the survey.

2. Property Description and Methodology

- 2.1 The property comprises of a single storey building with pitched and flat roofs.
- 2.2 The subjects are of masonry construction. Roofs are covered with natural slate and clay ridge tiles to pitched roofs with mineral felt and GRP to flat roofs, rainwater goods are half round cast iron and upvc gutters and downpipes with cast iron hopper heads to the front elevation. External walls are of natural stone and masonry construction with a roughcast finish to some elevations. Floors comprise concrete slab and suspended timber. Windows are a combination of aluminium with powder coated internal finish and UPVC, all with double glazed units. External doors are timber.

Internally, ceilings are a combination of painted plaster, lath and plaster, plasterboard, suspended ceiling tiles and fibre tiles, walls are painted plaster, lath and plaster, plasterboard, plywood, wetwall, ceramic tile and timber linings at low level. Floor coverings comprise carpet, vinyl tiles, sheet vinyl and concrete slab. Internal doors comprise timber hollow core and solid core doors with glazed panels and a variety of plastic, brass and aluminium ironmongery.

The heating system comprises 2 floor standing oil fired cast iron boilers, steel pipework, which is only insulated in parts, cast iron column radiators, a small number of replacement steel panel radiators and basic, dated, controls. A further small number of electric fan convector heaters supplement the heating system in various rooms. These are independently locally controlled by manual switches.

Heating oil is stored and supplied to the boilers from a polypropylene storage tank situated in an external bunded store. Basic, dated, oil safety controls are installed and supply pipework is dated.

Hot water is generated by electrical element heaters. The building is divided into a number of zones, which incorporate individual hot water storage cylinders and point of use water heaters. Generally, 7 litre storage volume types. Distribution pipework throughout the building is copper and is only insulated in parts.

Cold water is stored and supplied to a percentage of the school outlets and to the kitchen hot water storage cylinder via an insulated storage tank, located in the attic space above the dining hall. Distribution pipework throughout the building is generally copper and is only insulated in parts.

Mechanical ventilation is supplied to a small number of rooms by means of electrical extract fans. Fans vary in sized output and are wall and window mounted types controlled by local manual switching only.

A number of destratification fans are installed in classrooms. These are controlled via manual local switches only.

The electrical installation comprises concealed general wiring, assumed MICC, from dated distribution boards located in electrical cupboards 1/27 and 1/28 and also the janitors office / store room. Wiring accessories are generally white plastic flush and surface type sockets and switches in rooms, with a small number of rooms having metal clad surface mounted switches and sockets.

The lighting system consists of various types of fluorescent tube style fittings. These range generally from surface linear batten types in classrooms, to compact decorative glass diffused types in corridors. All lighting is manually controlled via local switches only.

A modern emergency lighting system has been installed in 2017, throughout the building. This system also incorporates external emergency lights, generally at building exits. Emergency exit sign lights are also installed, generally on escape routes and at emergency exits.

External building light comprises a mixture of bulkhead style fluorescent fittings and a number of halogen floodlights. External lights are controlled via a timeclock and there appears to be no lux sensors built in to the light fittings for automatic external light level control.

A modern smoke detection and alarm system has recently been installed in 2017, incorporating addressable multi zone control panel, call points, generally at emergency exits and on escape routes and combined detector and sounder heads located within rooms and spaces around the building interior.

A modern intruder alarm system is installed, consisting of 2 separate user control panels and PIR motion sensors located around the internal spaces of the building, generally at potential intruder entry points.

CCTV consisting of one external fixed camera is installed. Camera images are viewable on a monitor/processor unit in the reception office.

An intercom door security keypad is installed at the main entrance lobby internal door. A handset in the reception office allow building staff to control access to this door.

2.3 Building size – The properties GIFA is 900m².

2.4 Condition codes and priority categories.

CONDITION SUMMARY MATRIX	
Good - A	Performing well and operating efficiently
Satisfactory - B	Performing adequately but showing minor deterioration
Poor - C	Showing major defects and/or not operating adequately
Bad - D	Life expired and/or serious risk of imminent failure
N/A	Not applicable for assessment

PRIORITY RATING MATRIX	
1	Must Do (immediate) to address essential H&S/comply with law/avoid service disruption.
2	Should Do (within years 1 and 2) to achieve/maintain basic standards.
3	Would Do (within years 3 to 5) desirable works if affordable.
4	Programmed (within years 6 to 25) consider within Planned Maintenance.

3. Summary of Principal Considerations

3.1 Primary School Building

- Several slipped and broken slates.
- Broken ridge tiles and missing pointing.
- Felt roofing is reaching the end of its useful life.
- Surface corrosion of cast iron rainwater goods.
- Significant cracking to most elevations of external walls.
- Several double glazed units are blown and fogged with moisture between the panes.
- Plaster and lath & plaster ceilings are cracked.
- Plaster and lath & plaster walls are cracked.
- Suspended timber floors creak and are uneven.
- Carpets are soiled, stretched and wrinkled.
- Linoleum floor finishes are cracked and breaking up.

3.2 Mechanical and Electrical Installations

- Boilers and heating system are life expired as per CIBSE doc M and in poor condition.
- Internal lighting is life expired as per CIBSE doc M and in poor condition.
- Hot water storage vessels are life expired as per CIBSE doc M and in poor condition.
- 1/32 Toilet, 1/25 girls toilet, 1-13 girls toilet, 1/12 Access WC, 1/24 Boys toilet, have no mechanical extraction fans installed.
- Extract fans are not automatically operated by motion or humidity sensor.
- Electrical wiring and distribution boards are life expired as per CIBSE doc M and in poor condition.
- Electrical accessories are life expired as per CIBSE doc M and in poor condition.
- External building lighting is life expired as per CIBSE doc M and in poor condition. External lighting also has no automatic lux control sensors to operate lighting automatically according to external light levels.
- Hot and cold water pipework is only partly insulated.
- Hot and cold water pipework is reaching the end of its useful life due to age and condition.
- Oil supply pipework and safety controls are life expired as per CIBSE doc M and in poor condition.
- Heating system pipework is only partly insulated.

3.3 External Areas

- Cracks, potholes and surface erosion of tarmacadam car park and playground.
- Cracked, spalling render and missing pointing, to perimeter walls.

4 Conclusion

4.1 A brief summary of the elements condition.

Element	Condition	Priority
Roofs	C	3
Floors & Stairs	C	3
Ceilings	C	3
Ext. Walls, Windows & Doors	C	2
Internal Walls & Doors	C	3
Sanitary Services	B	4
Mechanical	D	1
Electrical	C	2
Decoration	C	3
Fixed Int. Facilities	B	4
External Areas	C	2
Outdoor Sports Facilities	N/A	

This information must be transferred to the Master Core Fact Sheet.

4.2 Improvements Recommended

- Provide sink base units below all sinks.
- Provide access to all pitched roof voids.
- Improve insulation in all roof voids.
- Expand field of CCTV cameras.
- Upgrade lighting to LED fittings with PIR controls.
- Upgrade heating. Options appraise to design optimum heat source.
- Upgrade external lighting to incorporate lux level demand control.
- Upgrade hot water systems to reduce unnecessary volume of stored water.
- Install extract fans in 1/32 Toilet, 1/25 girls toilet, 1-13 girls toilet, 1/12 Access WC, 1/24 Boys toilet.
- Insulate heating, hot and cold distribution pipework.

Appendix A

Limitations and Exclusions

Introduction

We will not seek to impose any particular limitations upon the survey work beyond those of normal surveying practice.

We will carry out a detailed, non-disruptive, visual inspection of the exposed parts of the building fabric that are readily and safely accessible at the time of our survey, using our standard survey equipment.

Our report will express our opinion on the condition and standard of construction of the inspected parts of the property and recommend further investigation or repair where necessary.

The survey will be limited to the subject property and no responsibility will be accepted for any defects that might materially affect the property, which are out with the scope of the survey.

Health and Safety

The inspection will be executed in a fashion in compliance with the Health & Safety at Work, etc Act 1974. Unless otherwise stated, it will be done without the benefit of internal or external scaffolding, guard rails or mechanical hoists. The external inspection will, therefore, be limited to ground level to inspection from accessible opening in the external fabric, or by the use of a 5 metre sectional ladder.

Deleterious Materials

Testing of components or taking of samples will not be taken through our inspection. If the presence of deleterious materials is suspected in the construction of the building, we will recommend further investigations are carried out by the appropriate specialists. Our inspection does not constitute an asbestos survey in accordance with the Control of Asbestos at Work Regulations.

Services

We will carry out a visual inspection of the primary service installations to include electrical and mechanical services where accessible. No tests of existing services will be undertaken at the time of our inspection. If, as a result of inspection and where considered necessary, we will advise if further investigations and reports should be obtained by independent specialists.

Unless agreed beforehand, our inspection will not comment on the suitability of the property for any use and the client is, therefore, advised to ensure that their use is possible and all processes, trades and activities are viable and permitted. No enquiries will be made to any local or statutory authority regarding any form of "Notice" that might have been served on the property at any time in the past or present. Similarly our report excludes any investigation into the structural design and suitability and compliance with legislation relating to buildings.

Environmental Conditions

The scope of the survey will be limited by the particular weather conditions pertaining at the time of inspection and no guarantee will be given with regard to the performance of the elements of the building during different conditions.

Where existing, the external inspections will be limited by the presence of any coverings of vegetation and no stripping off of the vegetation, including ivy, trellises, etc will be undertaken.

Contamination and Pollution

We will not make enquiries or investigations as to whether the property or any part of it or any neighbouring property appears on any register of contaminated land or might be contaminated or otherwise affected within the scope of the Environmental Protection Act 1990 or other legislation. We will, therefore, be unable to report that the property is free from risk in this respect. For the purpose of our report we will assume that such enquiries would reveal nothing which would affect the terms of our report.

Confidentiality and Use.

Our report is for the sole use of Moray Council and is confidential to the Council and their Professional Advisors. It should not be reproduced in whole or in part or relied upon by a Third Party for any purpose without the express prior written consent of Moray Council.

It should be understood that the report must not be used as any form of specification. Prior to the selection of an appropriate specification, it is likely that further investigation and exploratory works will be required following on from the survey in order to determine the full extent of the specification works necessary prior to submission to contractors for pricing.

Appendix B

Record Photographs

Roofs



1. Roof space access above P1, 2 & 3



2. Recessed roof space access



3. Roof structure, south pitch



4. Sarking boards



5. Replacement sarking boards



6. Roof space access above Dining Room



7. Roof structure



8. Sarking boards



9. Irregular roof surface



10. Raised roof surface



11. Slipped and broken slates



12.



13.



14.



15. Missing slate piece



16. Damaged clay ridge tiles



17.



18. GRP roof above Kitchen



19. GRP roof, soiled



20. GRP roof outlet



21. Felt roof – debris and vegetation



22. Moss on felt roof



23. Falls on felt roof



24. Surface erosion of felt roofs



25. Vent cap above staff toilet



26. GRP domed rooflights



27. UV degradation of domed rooflights



28. Distorted seals to rooflights



29. Insulation to south pitched roof



30.



31. Insulation above Dining Hall



32. Missing insulation, damaged lath & plaster



33. UPVC gutters



34. Cast iron gutters



35. Some gutters require cleaning



36. Cast iron hopper heads and downpipes



37. Cast iron downpipes



38. Cracked, corroded downpipes



39. Impact damaged cast iron



40. UPVC downpipes



41. Cast iron SVP's



42. Damaged UPVC SVP's



43. Boiler House chimney



44. Redundant stone chimneys



45. Roughcast chimney



46. Missing pointing to copes



48. Redundant bell tower (no bell)

External Walls



49. Cracking to external walls



50. Cracked concrete window sills



51. Cracking to external walls



52. Slipped masonry above DPC



53. Some underfloor vents at ground level



54. Roughcast external walls



55. Cracking of roughcast finish



56.



57. Cracked, spalling roughcast finish




58. Missing roughcast at bellcast bead



59. Timber doors to Nursery



60. Door to Girls Toilet



61. Previous repairs to timber door frame



62. Rot in timber door frames



63. Timber front entrance door



64. Timber back door



65. Redundant door to Boys Toilet



66. Paper packing around door



67. Timber louvre door to Boiler House



68. Rot at bottom of door



69. Rot in door frame



70. Large aluminium windows



71. Standard aluminium windows



72. Failed sealant below window sills



73. Windows with powder coated internal finish



74. Windows taped where seals have failed



75. ruPVC windows



76. Velux windows



77. Velux light wells



78. Failing solar film



79. Double glazing to aluminium windows



80. Fogged double glazing units



81. Broken glass



82. Double glazing to uPVC windows



83. Window lever handles



84. Handles to uPVC windows

External Decoration



85. Cast iron rainwater goods



86. Handrails

Steps and Ramps



87. Concrete steps



88.



89.



90. Steps to Boiler House



91. Concrete ramp to front entrance



92. Concrete ramp to Nursery



93.



94. Paving slab ramp



95. Damaged slabs



96. Damaged kerb wall



97. Guard rails



98.

Floors



99. Sloping timber floors



100.



101. Sheet vinyl flooring



102.



103.



104.



105. Damaged linoleum flooring



106.



107. Vinyl tiles



108. Soiled carpets



109. Wrinkled, stretched carpets



110.



111. Worn, soiled carpet



112. Open carpet joints



113. Worn concrete floors – Boiler House



114. Cracked concrete floor – Boys Toilet



115. Concrete steps - Nursery


Ceilings



116. Suspended ceiling tiles



117.



118. Reduced suspended ceiling height



119. Plasterboard ceilings – failed taped joints



120.




121. Plasterboard repairs



122.



123. Ceiling tiles - Kitchen



124. Plaster ceilings



125. Redundant vent in Staff Toilet ceiling



126. Repairs to plaster ceilings



127.



128. Damaged lath & plaster ceilings



129.



130. Concrete ceilings – Boiler House



131. Borrowed lights – Central corridor

Internal Walls



132. Plastered walls with wallpaper



133. Cracks at high level



134.



135.



136.



137.



138.



139. Plywood wall linings



140. Timber linings to dado level



141. Wetwall to the Kitchen



142. Ceramic wall tiles – Boys toilet



143. Ceramic tile splash backs



144. Timber framed borrowed lights



145. Single glazed



146. Timber window sills and surrounds



147.



149. Timber double doors (various)



150.



151.



152.



153. Timber double cupboard doors



154. Timber single doors (various)



155.



156. Classroom doors and screens



157. Wear and damage to classroom doors



158. Toilet cubicle timber doors



159. Door ironmongery (various)



160.



161.



162.



163.



164.


Sanitary Ware



165. Individual urinals



166. China cistern



167. Pupil WC



168. Staff WC



169. Nursery WC



170. Boys vanity basins



171. Wall hung basins (various)



172.



173.



174. Basins in Girls Toilet



175. PVC shower tray



176. PVC waste pipes



177. Copper waste pipes (Girls Toilet)



178. Accessible toilet



179. Cubicle partitions



180. Indicator bolts



181.



182. Vanity basin worktop (Boys Toilet)



183. Commercial kitchen



184.



185. Stainless steel classroom sinks



186. Inset stainless steel sinks



187. Hand wash sinks



188. Cleaners butler sink



189. PVC waste pipes

Internal Decoration



190. Previous repairs



191. Peeling paint



192.



193. Damaged decoration



194. Scraped and chipped



195.



196.



197.

Furniture



198. Classroom tables and chairs



199.



200. Base units and worktops



201. Worktop only, no base units



202. Missing handles, damaged base units



203. Staff room furniture

Mechanical and Electrical Photographs



204. Oil fired boilers. Plant room 0/1



205. Boiler flues into brick chimney. Plant room 0/1



206. Pipework – heating system. Plant room 0/1



207. Pipework – heating distribution. Typical.



208. Heating controls – plant room 0/1



209. Electric fan heater - kitchen



210. Radiator – cast iron column. Classroom



211. Radiator – cast iron section classroom



212. Hot water storage cylinder. Kitchen cupboard



213. Hot water storage cylinder. Cleaners/boys toilets.



214. Hot water storage cylinder – Girls toilets.



215. Point of use hot water heater. Typical.



216. Cold water storage tank. Above dining hall.



217. Pipework – cold water. Girls toilets.



218. Oil storage tank in external bunded secure store.



219. Oil supply auto shut off valve and pipework.
0/1



220. Extract fan – reception office.



221. Extract fan – staff toilets.



222. De stratification fan - classroom



223. De stratification class fan typical.



224. Switchgear and distribution boards.



225. Distribution board and supply general wiring.



226. Distribution boards



227. Fused isolators. Switchgear.




228. Sockets – typical.



229. Sockets – playgroup room 1/11



230. Lighting – corridor typical.



231. Lighting – classroom typical.



232. Lighting – reception office.



233. Lighting – dining hall.



234. Emergency lighting – typical.



235. Emergency exit sign lighting. Typical.



236. External lighting – typical.



237. External lighting.



238. Fire alarm system control panel. Entrance lobby.



239. Fire alarm system call point. Typical.



240. Fire alarm system wiring and detector head.
0/1




241. Fire alarm system detector head. Classroom.



242. Intruder alarm keypad – entrance lobby.



243. Intruder alarm keypad 2 – kitchen.



244. Internal access – security door keypad.
Entrance



245. Security door access handset – reception
office.



246. Period bell programmer – corridor.



247. Period bell – typical example.



248. Phone system – reception office.



249. Entrance door magnet – control panel.



250. External CCTV camera.



251. CCTV monitor and processor.

External Areas



252. Tarmacadam car park



253. Surface cracking



254. Surface erosion and potholes



255. Tarmacadam playground



256. Sunken surface



257. Surface cracking



258. Playground equipment



259. Tables and benches




260. Metal railings to car park



261.



262. Galvanised railings to playground



263.



264. Timber fence to playground



265. Boiler House metal railings



266. Extensive corrosion



267. Galvanised vehicle gate to playground



268. Galvanised pedestrian gate



269. Timber gate



270. Metal gate from car park



271. Corroded, broken post



272. Extensive corrosion



273. Timber gates to bin store



274. Metal railing gate with extensive corrosion



275. Coping to low level wall - cracked



276. Stone rendered wall



277. Render spalling



278. Missing pointing



279. School signage



280. Signage at front entrance



281. Car park road gully



282. Car park channel drain



283. Surface water gullies at downpipes



284. Playground road gully



285. Gullies at downpipes, blocked



286. Bin store enclosure



287. Oil tank enclosure



288. Bike shelters



289. Corroded metal frame



290. Bike lock-ups



291. Timber shed