

Summary Building Condition Survey Report

of

**Seafield Primary School
Deanshaugh Terrace, Elgin IV30 4ES**

24th to 26th May 2023



CONTENTS

01 – Introduction

02 – Property Description and Methodology

03 – Summary of Condition / Key Issues

04 – Conclusion

Appendices:

A – Limitations and Exclusions

B – Photographic Schedule

1. Introduction

- 1.1. This report has been prepared by Andrew Clark MRICS, MCIOB and Neal Stewart Building Services Engineer, of Moray Council. The report is confidential to Moray Council and is not intended for public release without Moray Council's express approval. The report summarises the condition of the property condition at the time of the survey, periodic reviews of material condition will be required. An inspection of the property was undertaken between Wednesday 24th and Friday 26th May 2023.
- 1.2. The report seeks to provide a brief summary of the condition of repair, identifying the principal defects and wants of repair, together with the main points of concern arising from the inspection. Items of a routine or minor maintenance nature have generally not been listed.
- 1.3. At the time of our inspection, the weather conditions were hot dry and windy.
- 1.4. The premises comprise a primary school with adjacent Hub and modular nursery. The primary school is constructed over single and two storeys, with the Hub and nursery being single storey. The primary school was constructed circa 1953 and extended circa 1976. The Hub was constructed circa 1987 with the nursery being added circa 2017.
- 1.5. The property was occupied during our inspection which was thus limited by the nature and extent of fixtures and fittings and of decorative finishes. In particular, the existence of fitted floor finishings throughout limited any inspection of the underlying floor structure. Framing out of walls and plasterboard linings conceal the underlying structure and it is possible that defects relating to moisture ingress may exist which are not revealed internally. Please also note and consider the Limitations and Exclusions Section, which is appended to this report.
- 1.6. Accessible flat roofs were examined from a standard 3.80m ladder, the flat roofs above the Games Hall and two storey parts were examined with the use of a drone. Access was provided to all internal areas with the exception of the external store behind the playground shelter.
- 1.7. All mechanical and electrical building services were inspected as far as reasonably practical. Domestic water supply pipework, heating pipework, alarm systems cabling and small power systems cabling was in most cases concealed in internal walls or under floor spaces and not reasonably practical to inspect. An effort has been made to assess the age and likely condition of these elements by using historic data, where available, to pinpoint the likely age of materials.
- 1.8. Extract and supply fan ventilation systems were tested by switching on and observing operation only. A detailed inspection of fan units, ductwork or controls has not been carried out during the non-intrusive survey.
- 1.9. Fire and intruder alarm systems were visually inspected for condition and age as far as reasonably practical and no physical testing was carried out on these services during the survey.

2. Property Description and Methodology

- 2.1 The property comprises of three, single and two storey buildings with flat roofs.
- 2.2 The subjects are of masonry construction to the primary school and Hub with timber framed construction to the modular nursery. Roofs are covered with single ply membrane, metal standing seam and profiled metal to flat roofs with glass and polycarbonate canopy roofs. Rainwater goods are UPVC to the primary school and Hub with metal box gutters and downpipes to the nursery. External walls are of masonry construction, overlaid with external insulation and composite steel faced cladding panels to the nursery. Floors comprise concrete slab and suspended timber to the ground floor and suspended concrete to the upper floor. Windows are powder coated metal over a timber structure to the primary school and Hub with powder coated aluminium windows to the nursery, all with double glazed units. External doors are similar to windows, powder coated metal over a timber structure to the primary school and Hub with powder coated aluminium doors to the nursery.

Internally, ceilings are a combination of painted plaster, painted plasterboard and suspended ceiling tiles, walls are painted plaster, painted plasterboard, fibreboard, brickwork, timber linings at low level, wetwall and ceramic tiles. Floor coverings comprise carpet, carpet tiles, sheet vinyl, timber flooring and concrete slab. Internal doors are generally hollow core timber with glazed panels and brass ironmongery to the primary school with solid core double fire doors to corridors. Timber veneered doors with glazed panels and aluminium ironmongery to the Hub and nursery.

The heating system for the main school and modular nursery buildings consists of 6 modular, natural gas, condensing boiler units, steel insulated pipework and a mix of conventional steel panel and low surface temperature radiators. The control system for these 2 buildings is a Trend building management system. The modular nursery building has its own heating timeclock to allow secondary control from the main building system.

An independent condensing, natural gas boiler, with steel, insulated pipework and steel panel radiators provide the heating system for the school Hub building. Controls are local to the hub building.

Both building boiler houses have automatic gas safety shut off controls installed, including carbon monoxide and methane gas detectors, together with fire detection and safety push stop buttons.

Gas pipework to both plant rooms is steel painted Ochre and has been recently installed from the on-site gas meters, circa 2017.

Domestic hot water is also generated by the gas boilers in the main school and for the modular nursery building. 2 separate storage calorifiers located in the main plant room and kitchen store cupboard store and distribute hot water around the building via pumped circuits of steel/copper, insulated pipework.

Hot water in the Hub building is heated by the gas boiler and stored and distributed by an unvented storage cylinder via copper/steel insulated pipework. All hot water systems have electric immersion heater back-up systems.

Cold water is distributed round the 3 school buildings directly from the mains supply, via copper/steel insulated pipework. No storage tanks are installed.

Mechanical general ventilation is provided in selected rooms and spaces of all 3 buildings by various types of electrical extract fan units. These range from wall mounted 4 inch types to 12 inch roof mounted units. Controls for these fans vary from PIR room sensors to manual on/off switches.

Electric motor opening windows are installed in the modular nursery building for the high level corridor and classroom windows. These units are controlled by manual switches.

Passivent roof mounted, windcatcher units are also installed in the modular nursery building with automatic and manual controls available.

The main school kitchen has a stainless steel extract canopy installed above the centre island cooking appliances, with 2 roof mounted fan units. The fan controls allow users to enable the fans and also set the speed required.

The electrical installation has been recently renewed and upgraded circa 2017. New main panel board, distribution boards, sub mains cabling, general wiring and accessories have been installed throughout all 3 buildings.

The lighting system throughout all 3 buildings was also renewed in circa 2017 with varying styles of LED fittings installed. Controls are generally automatic sensor activation. A small number of fluorescent tube and pendant style bulb fittings remain in the main school building, mainly in a small number of store cupboards only. Emergency lighting is installed throughout all 3 buildings, generally with self-contained, non maintained, variants of the general light fittings. Maintained, emergency exit sign lights are installed, dedicated at emergency exits and on escape routes.

LED external building lighting is installed around the perimeter of all 3 buildings. These are controlled by timeclock and are assumed to incorporate lux sensors. Each building lighting circuit appears to be independent from each other.

A modern smoke detection and alarm system is installed throughout all 3 buildings. Each building has its own addressable control panel, smoke/heat detectors, call points and interfaces to disable plant and automatic doors in the event of system activation.

Modern intruder alarm systems are installed throughout all 3 buildings. User keypads and PIR devices are installed, generally at potential intruder entry points.

Door access control security systems are installed throughout all 3 buildings. Videx and Paxton electromagnetic door units allow building users to control access to both external and internal doors of the school. Digitally programmed swipe cards issued by the school, allow permitted users to access internal school areas.

A modern CCTV system is installed, consisting of internal and external cameras, generally in the main school building and playground.

2.3 Building size – The properties GIFA is:

Primary School	- 2701m2
The Hub	- 369m2
Nursery	- 583m2
Total GIFA	- 3653m2

2.4 Condition codes and priority categories.

CONDITION SUMMARY MATRIX	
Good - A	Performing well and operating efficiently
Satisfactory - B	Performing adequately but showing minor deterioration
Poor - C	Showing major defects and/or not operating adequately
Bad - D	Life expired and/or serious risk of imminent failure
N/A	Not applicable for assessment

PRIORITY RATING MATRIX	
1	Must Do (immediate) to address essential H&S/comply with law/avoid service disruption.
2	Should Do (within years 1 and 2) to achieve/maintain basic standards.
3	Would Do (within years 3 to 5) desirable works if affordable.
4	Programmed (within years 6 to 25) consider within Planned Maintenance.

3. Summary of Principal Considerations

3.1 Primary School Building & Old Nursery

- The original timber internal doors are reaching the end of their useful life.
- Steel structure below the stage has considerable surface corrosion.
- Several carpets are soiled and stained.

3.2 Mechanical and Electrical Installations

- Ceiling mounted electric radiant panel heaters in the main school kitchen are life expired and should be considered for replacement.

3.3 External Areas

- Tarmacadam car park and access road are breaking up and pot holed.
- External concrete steps and ramps are cracked and eroded.
- Tarmacadam and paving slab footpaths are cracked and uneven.
- Damage and corrosion to metal gates and chain link fencing.

4 Conclusion

4.1 A brief summary of the elements condition.

Element	Condition	Priority
Roofs	B	4
Floors & Stairs	B	4
Ceilings	B	4
Ext. Walls, Windows & Doors	B	4
Internal Walls & Doors	C	3
Sanitary Services	B	4
Mechanical	A	4
Electrical	A	4
Decoration	B	3
Fixed Int. Facilities	B	4
External Areas	C	3
Outdoor Sports Facilities	B	4

This information must be transferred to the Master Core Fact Sheet.

4.2 Improvements Recommended

To prevent or reduce, vandalism / damage / accelerated deterioration.

- Protection of the external insulation is recommended in the car park area.
- Consider additional bird deterrents, 4 gull nests found on roofs.
- Confirm operational condition of bird scarer on nursery roof.

Appendix A

Limitations and Exclusions

Introduction

We will not seek to impose any particular limitations upon the survey work beyond those of normal surveying practice.

We will carry out a detailed, non-disruptive, visual inspection of the exposed parts of the building fabric that are readily and safely accessible at the time of our survey, using our standard survey equipment.

Our report will express our opinion on the condition and standard of construction of the inspected parts of the property and recommend further investigation or repair where necessary.

The survey will be limited to the subject property and no responsibility will be accepted for any defects that might materially affect the property, which are out with the scope of the survey.

Health and Safety

The inspection will be executed in a fashion in compliance with the Health & Safety at Work, etc Act 1974. Unless otherwise stated, it will be done without the benefit of internal or external scaffolding, guard rails or mechanical hoists. The external inspection will, therefore, be limited to ground level to inspection from accessible opening in the external fabric, or by the use of a 5 metre sectional ladder.

Deleterious Materials

Testing of components or taking of samples will not be taken through our inspection. If the presence of deleterious materials is suspected in the construction of the building, we will recommend further investigations are carried out by the appropriate specialists. Our inspection does not constitute an asbestos survey in accordance with the Control of Asbestos at Work Regulations.

Services

We will carry out a visual inspection of the primary service installations to include electrical and mechanical services where accessible. No tests of existing services will be undertaken at the time of our inspection. If, as a result of inspection and where considered necessary, we will advise if further investigations and reports should be obtained by independent specialists.

Unless agreed beforehand, our inspection will not comment on the suitability of the property for any use and the client is, therefore, advised to ensure that their use is possible and all processes, trades and activities are viable and permitted. No enquiries will be made to any local or statutory authority regarding any form of "Notice" that might have been served on the property at any time in the past or present. Similarly our report excludes any investigation into the structural design and suitability and compliance with legislation relating to buildings.

Environmental Conditions

The scope of the survey will be limited by the particular weather conditions pertaining at the time of inspection and no guarantee will be given with regard to the performance of the elements of the building during different conditions.

Where existing, the external inspections will be limited by the presence of any coverings of vegetation and no stripping off of the vegetation, including ivy, trellises, etc will be undertaken.

Contamination and Pollution

We will not make enquiries or investigations as to whether the property or any part of it or any neighbouring property appears on any register of contaminated land or might be contaminated or otherwise affected within the scope of the Environmental Protection Act 1990 or other legislation. We will, therefore, be unable to report that the property is free from risk in this respect. For the purpose of our report we will assume that such enquiries would reveal nothing which would affect the terms of our report.

Confidentiality and Use.

Our report is for the sole use of Moray Council and is confidential to the Council and their Professional Advisors. It should not be reproduced in whole or in part or relied upon by a Third Party for any purpose without the express prior written consent of Moray Council.

It should be understood that the report must not be used as any form of specification. Prior to the selection of an appropriate specification, it is likely that further investigation and exploratory works will be required following on from the survey in order to determine the full extent of the specification works necessary prior to submission to contractors for pricing.

Appendix B

Record Photographs

Roofs



1. School overview



2. Single ply membrane (insulation sheets visible)



3. Single ply wrinkled in places



4. The Hub overview, dark patches are silt



5.



6.



7. The Nursery overview



8. Metal standing seam roof with bird scarer



9. Metal profile roof to shelter/garage



10. Glass canopy roof – School to Nursery



11.



12. Polycarbonate canopy to Nursery entrance



13. Bird droppings and vegetation



14. Moss and vegetation



15.



16. GRP Rooflights to Primary School



17. Internal view of rooflights



18. Rooflights to Nursery



19. Nursery Rooflights internally



20. Nursery sunpipes



21.



22. UPVC fascia boards



23. Plywood fascia boards



24. UPVC gutters



25. UPVC downpipes (isolated defects)



26. UPVC gutters



27. Flat roof box gutters



28. Flat roof rainwater outlets



29. Hopper heads, partially blocked with vegetation



30. Metal roof box gutters, partially blocked



31. Box gutters with standing water



32. UPVC downpipes (isolated defects)



33. Hopper heads with blockages



34.



35. Downpipes not discharging to drainage



36. Metal roof outlets



37. Metal hopper heads and downpipes



38. Downpipes miss-aligned with drainage



39. Boiler flue and terminals



40.



41. Water tank house roof



42. Water tank house

External Walls



43. Primary school underfloor ventilation



44.



45. The Hub – ground levels



46. Projecting external insulation



47. The Nursery platt and ground levels



48. Underfloor/frame ventilation



49. Primary school external insulation



50.



51. Timber lining boards



52. Boards close to concrete slab



53. External insulation to The Hub



54. Isolated areas of previous repair



55. Nursery – Metal composite panel walls



56. Powder coated single door



57. Powder coated door internally



58. Powder coated double door



59. Aluminium single door (Nursery)



60. Aluminium double door (Nursery)



61. Garage door



62. Timber double doors



63. Powder coated standard window



64. Powder coated medium windows



65. Powder coated large windows



66.



67. High level windows (The Hub)



68. Powder coated windows (The Hub)



69. Aluminium windows (Nursery)



70. All windows are double glazed



71. Lever handles



72. High level mechanisms operated by winding handle

External Decoration



73. Peeling paint to base course



74. Staining to external insulation



75. Surface corrosion to metal gates



76. Surface corrosion to fence framework

Steps and Ramps



77. Concrete steps



78. Eroded concrete steps



79. Concrete ramps



80. Eroded concrete entrance ramp



81. Surface breaking up



82. Galvanised guard rails to ramps

Floors



83. Timber suspended floor of the stage



84. Corroded steel beams



85. Sheet vinyl in school



86.



87. Carpets in school



88. Soiled and stained carpets



89. Timber boarded sports floor



90. Painted concrete floors



91. Boiler room painted concrete floor



92. Sheet vinyl flooring in The Hub



93. Surface scuffs



94. Carpet flooring in The Hub



95. Sheet vinyl in Nursery



96. Carpet flooring in the Nursery



97. Concrete staircases




98. Plastered soffits



99. Sheet vinyl treads and risers



100.



101. Concrete stair to Boiler Room



102. Damaged stair nosings



103. Timber handrails



104. Metal balustrades with timber handrails

Ceilings



105. Primary school suspended ceiling tiles



106. Primary school plastered ceilings



107. Concrete ceiling, peeling paint



108. Plasterboard ceilings in The Hub



109. Nursery suspended ceiling tiles


Internal Walls




110. Plasterboard walls



111. Plastered walls (isolated hairline cracking)



112. Facing brick to Dining Hall



113.



114. Timber wall panelling in the primary school



115. Minor surface damage




116. Panelling to classroom walls



117. Wetwall in some toilet areas



118. Ceramic tile splashbacks



119. Isolated missing grout



120. Internal borrowed lights (toilets)



121. Typical timber hollow core door




122. Broken glazing beads



123. Damage to the surface of doors



124. Damage to door edges



125. Timber double doors



126. Not all are fire doors




127. Older timber double doors




128. Gaps with damage to edges




129. Traditional double swing doors



130. Damage to styles and bottom rails



131. Timber solid core veneered doors to The Hub and Nursery



132. Timber veneered double doors



133. Various glazing panels



134. Safety glass to replacement doors



135. Georgian wired glass to some doors



136. Isolated broken glass



137. Traditional brass ironmongery



138.



139. Aluminium ironmongery

Sanitary Ware



140. Stainless steel trough urinal



141. PVC cistern



142. School WC



143. Staff WC



144.



145. Nursery WC



146. Wall hung wash hand basin



147. China vanity basin



148. Accessible shower enclosures



149. Sheet vinyl shower tray



150. Accessible toilets



151. Stud wall cubicle partitions



152. Composite panel cubicle partitions



153. Composite vanity units



154. Isolated surface damage



155.



156. Commercial kitchen



157. Stainless steel kitchen sinks




158. Double bowl stainless steel sinks



159. Stainless steel inset sinks



160. Stainless steel wash hand basin



161. Cleaners butler sinks



162. PVC waste pipes

Internal Decoration



163. Plastered walls



164. Timber panelling



165. Timber floor boards



166. Timber doors



167. Timber joinery items

Furniture



168. Classroom desks and chairs



169.



170.



171.



172. Kitchen units



173. Sink base units



174. Cloakrooms



175. Coat hook rails



176. Staff room furniture



177. Stained seats

Mechanical and electrical photographs



178. Main school and modular building boilers.



179. Hub building gas condensing boiler.



180. Control panel main school boilerhouse.



181. Heating pipework and pumps hub building boiler house.



182. Radiator – typical throughout.



183. LST Radiator typical throughout.



184. Heating pipework main school boiler house.



185. Carbon monoxide detector hub boiler house.



186. Hot water calorifier – main school kitchen.




187. Hot water calorifier – main school boiler house.



188. Hot water storage tank – hub building.



189. Pressurisation unity – hub building.



190. Pipework – hot and cold main school typical.



191. Pipework – hot and cold typical throughout.



192. Extract fan main school roof mounted. Girls toilets.



193. Extract fan roof unit – main school external.



194. Extract fan – typical throughout all 3 buildings.



195. Extract fan – kitchen store main school.



196. Gas supply pipework and solenoid control valve – main school plant room.




197. Gas safety control panel – hub plant room.



198. Extract canopy – main school kitchen.



199. Extract fan terminals – main school kitchen on roof.



200. Main panel board – main school.



201. Distribution board LP1 main school.



202. Distribution boards – Hub building.




203. Distribution boards – modular nursery building.



204. Sub mains cabling – modular nursery plant room.




205. Sub mains cabling – main school.



206. General wiring – main school.



207. Wiring accessories – main school.



208. Wiring accessories – main school.



209. Wiring accessories modular nursery building.



210. Fire alarm control panel – modular nursery building



211. Fire alarm strobe – modular nursery building.



212. Fire alarm control panel main school.



213. Smoke detector – typical throughout 3 buildings.



214. Fire alarm control panel – hub building.



215. Fire alarm call point typical throughout.



216. Lighting – classroom typical main school.



217. Lighting – toilets and stores generally. Main school.



218. Lighting – PIR control main school typical.



219. Lighting – Hub classroom.



220. Lighting (with emergency self-contained) modular nursery building corridor.



221. Lighting – modular nursery toilet typical.



222. Lighting – main school hall.



223. Lighting – main school.



224. Intruder alarm PIR sensor – main school.



225. Intruder alarm system keypad main school.



226. Door security card reader unit. Main school




227. Door security control panels main school.



228. Security door entry keypad and video unit main school.



229. Security door system user handset and monitor screen main school.



230. CCTV camera main school.



231. CCTV system recorder and monitor main school.



232. Person hoist system – main school.



233. Passive windcatcher units – modular nursery.



234. Boiler flue roof termination – main school.



235. Boiler flue termination main school roof level.



236. External lighting modular nursery building.



237. External lighting modular nursery building.

External Areas



238. Access road to Kitchen breaking up



239. Tarmacadam potholed



240. Tarmacadam car park



241. Tarmacadam playground



242. Tarmacadam cracking



243. Playground furniture



244.



245. Tarmacadam footpaths



246. Cracking due to tree roots



247. Surface erosion



248. Paving slab footpaths



249. Uneven slabs



250. Concrete staircase to playing field



251. Broken nosings



252. Chain link fence leaning



253. Corroded steel frame



254. Impact damage to steel frame



255. Loose chain link fencing



256. Security mesh to The Hub and Nursery



257. Galvanised mesh fencing



258. Timber post and mesh fencing



259. Metal bar vehicle gates



260. Peeling paint and surface corrosion



261. Metal bar pedestrian gates



262.



263. Security mesh vehicle gates



264. Security mesh pedestrian gates



265. Timber boarded gates.



266. Galvanised bar gates



267.



268. Metal framed gates



269. Brick walls



270. Brick and roughcast walls



271. Broken coping stones



272. Cracks to brick walls



273. School signage



274.



275. Car park and playground drainage



276. Blocked surface water drainage



277. Caged bin enclosure



278. Metal profile and caged enclosure



279. Playground shelter and garage



280. Bike shelter



281. Cycle hoops



282



283. Timber sheds



284. Steel sheds



285. Timber utility pole



286.



287. Timber flag pole



288. General landscaping