



Summary Building Condition Survey Report

of

**St Sylvesters Primary School
Abbey Street, Elgin IV30 1DA**

26th & 27th June 2023



Z00454 / ADC & NS

CONTENTS

01 – Introduction

02 – Property Description and Methodology

03 – Summary of Condition / Key Issues

04 – Conclusion

Appendices:

A – Limitations and Exclusions

B – Photographic Schedule

1. Introduction

- 1.1. This report has been prepared by Andrew Clark MRICS, MCIOB and Neal Stewart Building Services Engineer, of Moray Council. The report is confidential to Moray Council and is not intended for public release without Moray Council's express approval. The report summarises the condition of the property condition at the time of the survey, periodic reviews of material condition will be required. An inspection of the property was undertaken on Monday 26th and Tuesday 27th June 2023.
- 1.2. The report seeks to provide a brief summary of the condition of repair, identifying the principal defects and wants of repair, together with the main points of concern arising from the inspection. Items of a routine or minor maintenance nature have generally not been listed.
- 1.3. At the time of our inspection, the weather conditions were hot, dry, windy and sunny.
- 1.4. The premises comprise a primary school constructed in a single storey. The school was constructed circa 1993.
- 1.5. The property was occupied during our inspection which was thus limited by the nature and extent of fixtures and fittings and of decorative finishes. In particular, the existence of fitted floor finishings throughout limited any inspection of the underlying floor structure. Framing out of walls and plasterboard linings conceal the underlying structure and it is possible that defects relating to moisture ingress may exist which are not revealed internally. Please also note and consider the Limitations and Exclusions Section, which is appended to this report.
- 1.6. Pitched and flat roofs were examined from ground level with the use of binoculars and with the use of a drone. Access was provided to all internal areas.
- 1.7. All mechanical and electrical building services were inspected as far as reasonably practical. Domestic water supply pipework, heating pipework, alarm systems cabling and small power systems cabling was in most cases concealed in internal walls or under floor spaces and not reasonably practical to inspect. An effort has been made to assess the age and likely condition of these elements by using historic data, where available, to pinpoint the likely age of materials.
- 1.8. Extract and supply fan ventilation systems were tested by switching on and observing operation only. A detailed inspection of fan units, ductwork or controls has not been carried out during the non-intrusive survey.
- 1.9. Fire and intruder alarm systems were visually inspected for condition and age as far as reasonably practical and no physical testing was carried out on these services during the survey.

2. Property Description and Methodology

- 2.1 The property comprises of a single storey building with pitched and flat roofs.
- 2.2 The subjects are of a steel frame with blockwork construction. Roofs are covered with Italian slate with snow boards to the main pitched roofs with metal profile sheets to the attached external store and corrugated asbestos to the external store at the front wall. Rainwater goods are half octagonal UPVC gutters with square UPVC downpipes. External walls are of stone clad masonry construction. Floors comprise concrete slab and timber floating floors. Windows are timber] with thin double glazed units. External doors are timber.

Internally, ceilings are painted plasterboard, walls are a combination of painted plaster, painted plasterboard, timber panelling at low level, wetwall and ceramic tiles. Floor coverings comprise carpet, carpet tiles, sheet vinyl and timber boards. Internal doors are generally solid core timber veneered with glazed panels and aluminium ironmongery.

The heating system comprises 3 x cast iron, non condensing natural gas fired boilers. Steel pipework allows pumped hot water to be circulated around the building, terminating in steel panel vertical and horizontal type radiators. Controls are basic and dated. Heating pipework is only insulated in parts.

Domestic hot water is also generated by the gas boilers and is stored and distributed through a pumped copper pipework loop, which is only insulated in parts. An approx. 300 litre calorifier located in the plant room, stores hot water and supplies it to meet the demands of the building.

Cold water is both directly mains fed and also via a storage tank, situated in the attic space. Copper pipework, which is only insulated in parts, conveys cold water supplies to outlets throughout the building.

Gas pipework is steel with and is branched to feed both the gas boilers and also cooking appliances in the main kitchen. Both areas have electrically operated gas solenoid valves, with basic safety controls for the plant room supply. The kitchen gas supply incorporates ventilation interlock devices.

Mechanical ventilation is installed throughout the building, with 3 separate air handling units, located in the attic space. The school hall has a designated air handling unit, as does the kitchen. A general air handling system otherwise provides supply and extract ventilation for toilets and other required spaces and rooms. A small number of domestic type extract fans are installed in a small number of other rooms.

In the main open access area 16 electrically operated windows allow building users to ventilate the building as required.

The Electrical installation comprises incoming supply and main fuses located in electric cupboard 1/11a. The main distribution board is also located here. Sub mains cabling supplies further distribution boards for the plant room and the main kitchen. General twin and earth wiring supplies flush plastic accessories throughout.

The lighting system comprises various styles of fluorescent tube fittings. These fittings are manually controlled by local switches only. External lighting comprises recessed 2D fluorescent tube fittings installed under the building eaves/soffit boarding. A small number of

pole mounted lantern style fittings and 1 flood light type are situated in the car parking area and around the back of the building.

Emergency lighting comprises self-contained variants of the general light fittings and also designated bulkhead fittings installed throughout. Emergency exit sign lights are also installed, generally at fire exits and on escape routes. The emergency lighting system is supplied by a central battery, wired independently of the main lighting circuits.

A Smoke detection and alarm system is installed, however this system is basic. This system comprises control panel, call points and sounders. Only 1 smoke/heat detector could be seen throughout the building.

An Intruder alarm system is installed, consisting of user control unit and PIR sensors, generally located at potential intruder entry points.

A number of security door access control systems are installed in the building. The main entrance is controlled by a Paxton system, comprising audio and video unit, card reader and emergency open unit internally. An audio handset and monitor situated in the reception office allows building staff to control access to this door.

3 other entrance doors also have Paxton systems, which require authorised cards to enable opening of the doors. Cards are supplied on authorisation by the school.

A modern CCTV system, comprising 2 external and 1 internal cameras is installed, with recording and viewing equipment located in the reception office.

2.3 Building size – The properties GIFA is 1131m².

2.4 Condition codes and priority categories.

CONDITION SUMMARY MATRIX	
Good - A	Performing well and operating efficiently
Satisfactory - B	Performing adequately but showing minor deterioration
Poor - C	Showing major defects and/or not operating adequately
Bad - D	Life expired and/or serious risk of imminent failure
N/A	Not applicable for assessment

PRIORITY RATING MATRIX	
1	Must Do (immediate) to address essential H&S/comply with law/avoid service disruption.
2	Should Do (within years 1 and 2) to achieve/maintain basic standards.
3	Would Do (within years 3 to 5) desirable works if affordable.
4	Programmed (within years 6 to 25) consider within Planned Maintenance.

3. Summary of Principal Considerations

3.1 Primary School Building

- Isolated broken slates.
- Missing snow boards.
- Metal profile roof requires cleaning.
- Plywood fascia is rotten to the external store, next to the Kitchen.
- Corrugated asbestos roof to external store is life expired.
- Timber windows have slight rot, double glazing is very thin.
- External timber doors have slight rot and are twisted.
- Plasterboard ceilings have isolated cracking at joints and failed taped joints.
- Timber floating floors creak (staff area)
- Carpet tiles are soiled, loose and lifting.
- Sheet vinyl flooring is scratched in isolated locations.
- Internal doors have surface scratches.
- Sink base units are life expired.

3.2 Mechanical and Electrical Installations

- The boilers and heating system are life expired as per CIBSE guidelines.
- Hot and cold water distribution pipework is not fully insulated.
- Kitchen air handling unit system is not readily accessible in the attic space.
- Kitchen cooking and dishwashing extract hoods are life expired as per CIBSE guidelines.
- Heating and ventilation control panel and accessories are life expired as per CIBSE guidelines.
- The electrical installation incorporating distribution boards, wiring and accessories is life expired as per CIBSE guidelines.
- Internal building lighting, associated wiring and controls are life expired as per CIBSE guidelines.
- The existing fire precaution and alarm system is life expired as per CIBSE guidelines and does not have an adequate field of detectors or other devices to comprehensively cover the building.

- The existing intruder alarm system is life expired as per CIBSE guidelines.
- The CCTV system field of cameras is small and only incorporates 3 cameras.

3.3 External Areas

- Access road is potholed and breaking up.
- Stone walls missing stones and surface/render erosion.
- Timber fences and gates are damaged and have minor rot.
- Car park drainage is blocked.
- Playground drainage damaged and blocked.

4 Conclusion

4.1 A brief summary of the elements condition.

Element	Condition	Priority
Roofs	B	4
Floors & Stairs	C	3
Ceilings	B	3
Ext. Walls, Windows & Doors	C	3
Internal Walls & Doors	B	3
Sanitary Services	B	4
Mechanical	C	2
Electrical	D	1
Decoration	C	3
Fixed Int. Facilities	C	3
External Areas	D	2
Outdoor Sports Facilities	B	4

This information must be transferred to the Master Core Fact Sheet.

4.2 Improvements Recommended

To prevent or reduce, vandalism / damage / accelerated deterioration.

- Increase the field of CCTV cameras.
- Install security access control system to back external door.
- Install BMS to cover M+E services.
- Upgrade cold water systems to eliminate storage tank.
- Upgrade hot water system to plate heat exchanger, to eliminate storage tank.
- Upgrade all lighting to LED fittings.
- Upgrade heating system to sealed system.
- Upgrade automatic gas safety control system in plant room.

Appendix A

Limitations and Exclusions

Introduction

We will not seek to impose any particular limitations upon the survey work beyond those of normal surveying practice.

We will carry out a detailed, non-disruptive, visual inspection of the exposed parts of the building fabric that are readily and safely accessible at the time of our survey, using our standard survey equipment.

Our report will express our opinion on the condition and standard of construction of the inspected parts of the property and recommend further investigation or repair where necessary.

The survey will be limited to the subject property and no responsibility will be accepted for any defects that might materially affect the property, which are out with the scope of the survey.

Health and Safety

The inspection will be executed in a fashion in compliance with the Health & Safety at Work, etc Act 1974. Unless otherwise stated, it will be done without the benefit of internal or external scaffolding, guard rails or mechanical hoists. The external inspection will, therefore, be limited to ground level to inspection from accessible opening in the external fabric, or by the use of a 5 metre sectional ladder.

Deleterious Materials

Testing of components or taking of samples will not be taken through our inspection. If the presence of deleterious materials is suspected in the construction of the building, we will recommend further investigations are carried out by the appropriate specialists. Our inspection does not constitute an asbestos survey in accordance with the Control of Asbestos at Work Regulations.

Services

We will carry out a visual inspection of the primary service installations to include electrical and mechanical services where accessible. No tests of existing services will be undertaken at the time of our inspection. If, as a result of inspection and where considered necessary, we will advise if further investigations and reports should be obtained by independent specialists.

Unless agreed beforehand, our inspection will not comment on the suitability of the property for any use and the client is, therefore, advised to ensure that their use is possible and all processes, trades and activities are viable and permitted. No enquiries will be made to any local or statutory authority regarding any form of "Notice" that might have been served on the property at any time in the past or present. Similarly our report excludes any investigation into the structural design and suitability and compliance with legislation relating to buildings.

Environmental Conditions

The scope of the survey will be limited by the particular weather conditions pertaining at the time of inspection and no guarantee will be given with regard to the performance of the elements of the building during different conditions.

Where existing, the external inspections will be limited by the presence of any coverings of vegetation and no stripping off of the vegetation, including ivy, trellises, etc will be undertaken.

Contamination and Pollution

We will not make enquiries or investigations as to whether the property or any part of it or any neighbouring property appears on any register of contaminated land or might be contaminated or otherwise affected within the scope of the Environmental Protection Act 1990 or other legislation. We will, therefore, be unable to report that the property is free from risk in this respect. For the purpose of our report we will assume that such enquiries would reveal nothing which would affect the terms of our report.

Confidentiality and Use.

Our report is for the sole use of Moray Council and is confidential to the Council and their Professional Advisors. It should not be reproduced in whole or in part or relied upon by a Third Party for any purpose without the express prior written consent of Moray Council.

It should be understood that the report must not be used as any form of specification. Prior to the selection of an appropriate specification, it is likely that further investigation and exploratory works will be required following on from the survey in order to determine the full extent of the specification works necessary prior to submission to contractors for pricing.

Appendix B

Record Photographs

Roofs



1. Steel frame externally



2. Steel columns & beams within roof space



3.



4.



5. Timber trussed roof



6. External store timber joists



7. Salt store timber joists



8. Overview of slated roof



9. Lichen on the surface of slates



10. Isolated broken slates



11. Lead valley gutters



12. Metal profile flat roof (external store)



13. Felt roof to gas meter house




14. Corrugated asbestos roof (salt store)



15. Lead ball finials



16.



17. Glass skylights above open plan area



18.



19. Electrically operated skylights




20. Timber snowboards



21. Missing section of snow boards



22. Rotten fascia board to external store



23.



24. Composite fascia & soffit boards



25. Mineral fibre insulation laid on ceilings



26. Insulation roll collapsed from sarking



27.



28. UPVC gutters with standing water



29. UPVC gutters and downpipes



30. Below ground drainage blocked

External Walls



31. Natural stone external walls



32.



33. Timber glazed entrance door



34. Timber glazed fire escape doors



35. Doors twisting, poor fit in frame



36. Solid core timber doors



37. Damage to face of doors



38. Thin double glazed units



39. Top hung timber windows



40. Large timber glazed screen



41. Typical series of windows



42.



43. Windows internally



44. Seals to frames failing



45. Thin double glazed units



46. Aluminium lever handles



47. Additional window stays

External Decoration



48. Snow boards



49. Timber roof ventilation grills



50. Timber external doors



51. Timber windows



52. Timber fencing



53. Timber gates

Steps / Ramps



54. Paving slab steps



55.

Floors



56. Sheet vinyl - soiled



57. Sheet vinyl to wet areas



58. Scuffed sheet vinyl



59. Edges lifting, seam joints failed



60. Soiled carpet tiles




61. Carpet tiles lifting



62. Carpet tiles soiled



63. Carpet tiles damaged



64. Carpet worn



65. Timber sports floor



66. Timber boards worn



67. Painted concrete floors



68.

Ceilings



69. Plasterboard ceilings



70. Previous fixings removed



71. Cracking at taped joints



72. Cracking at joints



73. Failed taped joints



74. Cracking at steel columns



75. Failed taped joints

Internal Walls



76. Steel framework



77.



78. Blockwork walls



79. Plasterboard walls



80. High level lattice panelling



81.



82. Timber linings to Games Hall walls



83. Wetwall to boys' toilets



84. Ceramic tiles to girls' toilets



85. Kitchen walls



86. Accessible toilet and shower enclosure



87. Ceramic tile splashbacks



88. Timber screen to Games Hall




89.



90. Screen glazed with Georgian wired glass



91. Timber doors




92. Door binding on frame



93. Double timber doors



94. Timber glazed doors



95.



96. Double timber glazed doors



97. Timber veneered doors



98.



99. PVC faced timber doors



100.



101. Georgian wired glass to doors




102. Aluminium ironmongery

Sanitary Ware



103. Single vitreous china urinals



104. China cisterns



105. Typical W.C.



106. Wall hung china basins



106. China vanity basins – Boys toilets



107. Sheet vinyl wet floor shower area



108. PVC waste pipes



109. Accessible toilet



110. Composite panel cubicle partitions



111. Lock mechanism



112. Edging coming loose



113. Composite vanity base units



114. Commercial kitchen



115. Stainless steel sinks



116. Cleaners Butler sinks



117. Crosshead wall mounted taps



118.



119. PVC waste pipes

Internal Decoration



120. Plasterboard ceilings



121. Plasterboard walls



122.



123.



124.



125. Concrete floors



126. Joinery items

Furniture



127. Classroom tables & chairs



128.



129. Worn worktops



130. Base units missing doors



131. Coat hook stands and benches



132. Staff room furniture



133. Chair fabric damage



134. Chairs soiled and stained

Mechanical and Electrical Photographs



135. Gas boilers – plant room



136. Flue system – boilers



137. Heating and ventilation control panel. Plant room



138. Pumps and pipework – heating system



139. Heating feed and expansion tank attic space



140. Pipework heating system typical internal.



141. Radiator heating system typical 1/11



142. Radiator vertical column type 1/11



143. Hot water calorifier plant room.



144. Pipework – hot water system typical.



145. Cold water storage tank internal view attic space



146. Pipework – cold water attic space.



147. Gas pipework plant room typical.



148. Gas pipework – kitchen supply attic space.



149. Extract fan – kitchen store.



150. Extract fan – cupboard next to kitchen.



151. Extract hood – kitchen.



152. Toilet extract fan system attic space.



153. Air handling unit attic space.




154. Kitchen air handling unit attic space.




155. Air conditioning indoor unit kitchen.



156. Air conditioning outdoor unit kitchen.



157. Electric windows – open area 1/11



158. Electric windows 1-11 open area.



159. DB LP 1 – Electric cupboard 1/11a



160. DB – emergency lighting 1-11a



161. DB – LP kitchen



162. DB – LP plant room.



163. Floor socket compartment boxes 1-11



164. Wall mounted flush socket typical.



165. Switches – typical. 1/11



166. Incoming power supply and hydro fuses 1/11a



167. Lighting – classrooms and circulation typical.



168. Lighting – sports hall.



169. Lighting – stores typical.



170. Lighting – boys and girls toilets typical.



171. Light switch control typical.



172. Lighting – circulation areas typical.



173. External car park lighting.



174. External building lighting typical.




175. Emergency lighting central battery



176. Emergency lighting boys toilets.



177. Emergency exit sign light front door.



178. Emergency self-contained light fitting typical.



179. Fire alarm system control panel.



180. Fire alarm system call point typical.



181. Intruder alarm system user control unit.



182. Intruder alarm system PIR.



183. Security door electro magnet unit typical.



184. Security door card reader and emergency release unit typical.



185. CCTV recorder and processor 1/24 office.



186. CCTV camera south end entrance.



187. CCTV camera internal.



188. CCTV camera East end entrance.

External Areas



189. Tarmacadam shared access road



190. Cracked and pot holed



191. Tarmacadam car park



192. Surface moss and vegetation



193. Tarmacadam playground



194. Playground benches



195. Playground benches and tables



196. Tarmacadam footpaths



197. Paving slab paths and courtyards



198. Cracked, loose and uneven slabs



199. Concrete steps



200. Timber framed mesh fencing



201. Timber framed mesh fencing



202. Timber boarded fencing



203. Metal railings



204. Chain link fencing



205. Metal rail gate



206. Timber boarded gates



207. Double timber boarded gates



208. Damage and rot to timber gates




209. Custom metal rail double gates



210. Galvanised double gates



211. Natural stone garden walls



212. Natural stone high walls



213. Masonry damage and erosion



214. Eroded, crumbling masonry



215.




216. Spalling cement mortar pointing



217.



218.



219. School signage



220. Concrete channel drain cracked and broken



221. Drainage gully broken and blocked



222. Concrete channel drain blocked



223.



224. Car park road gully blocked



225. Bike shelter



226. Gas meter house



227. Salt shed



228. Timber sheds



229.



230.



231. Timber bridge



232. Polytunnel



233. Play area 1



234. Play area 2



235. Hedges



236. Sports field