



Summary Building Condition Survey Report

of

**New Elgin Primary School
Bezack Street, Elgin IV30 6DP**

18th & 19th January 2023



Z00457 / ADC & NS

CONTENTS

01 – Introduction

02 – Property Description and Methodology

03 – Summary of Condition / Key Issues

04 – Conclusion

Appendices:

A – Limitations and Exclusions

B – Photographic Schedule

1. Introduction

- 1.1. This report has been prepared by Andrew Clark MRICS, MCIOB and Neal Stewart Building Services Engineer, of Moray Council. The report is confidential to Moray Council and is not intended for public release without Moray Council's express approval. The report summarises the condition of the property condition at the time of the survey, periodic reviews of material condition will be required. An inspection of the property was undertaken on Wednesday 18th and Thursday 19th January 2023 with a further roof survey carried out on Wednesday 15th February 2023.
- 1.2. The report seeks to provide a brief summary of the condition of repair, identifying the principal defects and wants of repair, together with the main points of concern arising from the inspection. Items of a routine or minor maintenance nature have generally not been listed.
- 1.3. At the time of our inspection, the weather conditions were freezing and windy with rain and snow showers.
- 1.4. The premises comprise a primary school, constructed in single and two storeys with single storey outbuildings. The school was constructed circa 1905, extended circa 1970 with a temporary building constructed circa 2008 and a new Nursery extension circa 2013. Although not "Listed" the school is on the Canmore register as a site of historic interest.
- 1.5. The property was occupied during our inspection which was thus limited by the nature and extent of fixtures and fittings and of decorative finishes. In particular, the existence of fitted floor finishings throughout limited any inspection of the underlying floor structure. Framing out of walls and plasterboard linings conceal the underlying structure and it is possible that defects relating to moisture ingress may exist which are not revealed internally. Please also note and consider the Limitations and Exclusions Section, which is appended to this report.
- 1.6. Pitched roofs were examined from ground level with the use of binoculars. Flat roofs were examined by drone survey, no access was gained to the flat roofs. Access was provided to all internal areas.
- 1.7. All mechanical and electrical building services were inspected as far as reasonably practical. Domestic water supply pipework, heating pipework, alarm systems cabling and small power systems cabling was in most cases concealed in internal walls or under floor spaces and not reasonably practical to inspect. An effort has been made to assess the age and likely condition of these elements by using historic data, where available, to pinpoint the likely age of materials.
- 1.8. Extract and supply fan ventilation systems were tested by switching on and observing operation only. A detailed inspection of fan units, ductwork or controls has not been carried out during the non-intrusive survey.
- 1.9. Fire and intruder alarm systems were visually inspected for condition and age as far as reasonably practical and no physical testing was carried out on these services during the survey.

2. Property Description and Methodology

- 2.1 The property comprises of single and two storey buildings with pitched and flat roofs.
- 2.2 The subjects are of masonry, concrete frame and timber temporary form construction. Roofs are covered with natural slate to pitched roofs, standing seam metal to the shallow pitch of the new Nursery and single ply membrane to all flat roofs. Rainwater goods are generally half round cast iron with ogee cast iron to part of the original school and ogee UPVC gutters to the ASN building. Pitched roofs have metal and timber skylights, flat roofs have GRP domed rooflights and a lantern cupola above the Kitchen. External walls are of natural stone, concrete frame and masonry infill panels, brickwork, roughcast and composite insulated metal panels. Floors comprise concrete slab, beam & block and suspended timber. Windows are UPVC and timber to the school buildings with powder coated aluminium windows to the new Nursery. All windows have double glazed units. External doors are timber and powder coated aluminium.

Internally, ceilings are a combination of painted plaster, painted plasterboard, fibre ceiling tiles, timber linings, concrete, composite panels and suspended ceiling tiles. Walls are painted plaster, painted plasterboard, ceramic tile and wet wall panels. Floor coverings comprise carpet, carpet tiles, vinyl tiles, sheet vinyl, timber boards, Terrazzo flooring and concrete slab. Internal doors are generally timber with glazed panels and timber hollow core doors to cupboards etc all with brass and aluminium ironmongery.

The heating system in the main school has recently undergone a number of phases of upgrade from 2017. New modular natural gas condensing boilers, carbon steel insulated pipework and upgraded controls, together with a mix of low surface temperature steel panel radiators, steel panel radiators and fan convector heaters, now provide heating to spaces and rooms of the main school building. In the nursery extension underfloor heating is installed in some rooms and low surface temperature steel panel radiators in the remaining rooms. In the independent ASN building, electric wall mounted convector heaters provide heating in the rooms and spaces. A small number of areas of the main school have not been upgraded for heating but it is assumed that these will follow in upcoming phases of ongoing work.

A Trend BMS system provides on-site monitoring and remote control for the heating system, through internet connection for permitted users.

Hot water is also generated by the new modular boilers in the main school. A recently installed stainless steel calorifier provides instantaneous heating and storage of domestic hot water, which is circulated around the main school building through a pumped, insulated, copper pipework circuit. In the nursery an independent copper hot water storage cylinder provides storage of domestic hot water, which is circulated around the nursery rooms via a pumped, insulated, copper pipework circuit. The source of heating for this hot water in the nursery is also from the boilers in the main school plant room, with a back up electrical immersion heater available if required.

Hot water in the independent ASN building is provided by 2 point of use electric water heaters. Hot water is distributed around the ASN building by copper pipework, which is mostly concealed.

Hot water distribution pipework has recently been upgraded in the main school although some areas are yet to be completed. It is assumed that these areas are to follow in upcoming phases of ongoing work.

Cold water is distributed around the main school by recently upgraded insulated copper pipework. Some areas of the main building are yet to be upgraded but are assumed to be pending in upcoming, ongoing phases of work. Cold water in the nursery is also distributed by copper, insulated pipework. The independent ASN building cold water distribution pipework is also insulated copper. Both the main building/nursery and ASN building cold water supplies are directly from the mains, with no cold water storage tanks now installed.

Gas supply pipework is welded, painted steel, which can only be seen in part due to being concealed under the floor space of the main school. It does not appear that gas pipework has been included in the scope of works for recent upgrades and should be monitored closely for future replacement, due to its age.

Mechanical ventilation is provided in the main school toilets and kitchen rooms by ceiling or wall mounted electrical extract fan of varying sizes and outputs. The nursery extension mechanical ventilation is provided by ceiling mounted electrical extract fans and also 2 heat recovery type ventilation systems.

Extract ventilation is provided in the ASN building toilets by electrical wall mounted extract fans. Controls for fans are generally local on/off switch only.

The electrical installation in the main school building consists of incoming power supply at the meter room 1/3. LV cabling carries power supplies to distribution boards from meter room 1/3 in the main school.

A number of distribution boards are located around the main school building and these distribute lighting and power supplies to local circuits through general wiring throughout the school. Separate distribution boards and circuits exist for both the nursery extension and ASN building. Wiring accessories are a mix of white plastic flush and surface mounted, to modern brushed steel and anthracite coloured switches and sockets in the nursery extension. The rooms within the ASN building have secondary consumer units installed to provide RCD socket protection.

The lighting system consists of varying styles of fluorescent tube style, recessed downlights and wall mounted up and down light fittings throughout the main school, nursery extension and ASN building. All internal lights are controlled via manual on/off switches only.

A modern smoke detection and alarm system is installed throughout the main school, with addressable control panel, detector heads and field devices. A good number of rooms in the main school have no detector heads installed.

The nursery extension also has modern fire system detector heads and field devices installed throughout. These devices are connected to the main school fire alarm control panel. The ASN building has a dated fire alarm control panel and field devices, which are linked to the main school control panel via a relay control switch installed in the ASN building.

A modern intruder alarm system is installed throughout the main school, consisting of user control panel and PIR field sensors, generally located at potential intruder entry points.

A separate intruder alarm keypad and field system of PIR sensors is also installed in the nursery extension.

A dated intruder alarm panel and system of field PIR sensors is installed in the ASN building, but it is not clear from the visual survey inspection, whether this system is working.

Security door entry control systems are installed at the main school internal entrance door, nursery extension entrance doors and also the main entrance of the ASN buildings. Both the nursery doors and the ASN main entrance are fob activated types, with the nursery and main school also having video and audio units to allow building staff to communicate with people before allowing entry.

Disabled toilet pull chord alarm systems have been installed in the access toilets within the main school, nursery and ASN building toilets respectively. These systems comprise pull chord for activation with remote indicator panels out with the toilets to alert building users.

A modern CCTV system is installed with external and internal cameras covering areas of the main school building and the nursery extension. Cameras of different ages and type are part of this system due to the system being extended through time. At the time of the survey only 6 cameras out of a total of 22 were working. This had been reported for attention and repair by the school.

2.3 Building size – The properties GIFA is 3,339m².

2.4 Condition codes and priority categories.

CONDITION SUMMARY MATRIX	
Good - A	Performing well and operating efficiently
Satisfactory - B	Performing adequately but showing minor deterioration
Poor - C	Showing major defects and/or not operating adequately
Bad - D	Life expired and/or serious risk of imminent failure
N/A	Not applicable for assessment

PRIORITY RATING MATRIX	
1	Must Do (immediate) to address essential H&S/comply with law/avoid service disruption.
2	Should Do (within years 1 and 2) to achieve/maintain basic standards.
3	Would Do (within years 3 to 5) desirable works if affordable.
4	Programmed (within years 6 to 25) consider within Planned Maintenance.

3. Summary of Principal Considerations

3.1 Primary School Buildings

- Slate roofs are in need of repair and reaching the end of their useful life.
- Roughcast finish has surface erosion, cracking and spalling in several areas.
- Brickwork repairs required to exposed brickwork.
- Timber windows are rotten in several locations.
- Timber external doors require routine maintenance.
- Suspended ceiling tiles are in poor condition in the original school.
- Plastered walls are cracked and spalling.
- Some carpets are soiled and worn.
- Some vinyl floors are cracked and worn, vinyl tiles are in poor condition.
- Internal doors are dated, damaged and reaching the end of their useful life.
- Vanity units in toilets are in need of repair.
- Several sink base units are dated and in poor condition.
- Original WC cubical panels are dated and damaged.
- Internal decoration is overdue and decoration of the timber lining boards is particularly poor.

3.2 ASN Base (Portacabin Type Building)

- Irregular fall on gutter.
- Missing/damaged rainwater downpipes.
- Plywood underbuilding screen damaged by rainwater penetration and wet rot.
- Guardrails to external ramps suffer from wet rot.

3.3 Mechanical and Electrical Installations

- Room 1/28 Gents toilet in main school has no mechanical extraction
- Main school fire alarm system is only part coverage and no smoke detectors are installed in a large number of rooms.
- General/emergency lighting in rooms G07/G08 internal and external stores in Nursery extension does not work correctly.
- Large entrance hall G09 in nursery extension has inadequate ventilation to keep CO2 levels down when fully populated with pupils.

- Gas supply pipework under floor space of main school is life expired as per CIBSE guide M for indicative life expectancy.
- Heating pipework and radiators in block ground and 1st floor is life expired.
- Hot and cold water distribution in block ground and 1st floor of main school is life expired.
- The upstand directly above the cookers in the main school kitchen requires cleaning on a regular basis. Kitchen staff state that this is not happening.
- The intruder alarm system in the ASN building does not appear to be working.
- The original BMS control panel and keypad in the main school plant room is life expired as per CIBSE guide M.
- A large number of CCTV cameras footage is not visible through the viewing monitor.
- General lighting in all 3 buildings is fluorescent tube type and could be upgraded for LED to save energy and prolong life of tubes / bulbs.

3.4 External Areas

- Paving slab footpaths cracked and broken.
- Playground drainage is blocked.
- Playground shelter requires concrete and brickwork repairs.

4 Conclusion

4.1 A brief summary of the elements condition.

Element	Condition	Priority
Roofs	C	3
Floors & Stairs	B	3
Ceilings	C	3
Ext. Walls, Windows & Doors	C	3
Internal Walls & Doors	B	3
Sanitary Services	B	4
Mechanical	B	4
Electrical	B	3
Decoration	C	3
Fixed Int. Facilities	C	3
External Areas	C	2
Outdoor Sports Facilities	B	4

This information must be transferred to the Master Core Fact Sheet.

4.2 Improvements Recommended

- Provide access to roof space above 1/34 to 1/37.
- Upgrade general lighting to LED to save energy and to reduce cost of bulbs and improve lux levels. Associate with automatic on/off sensor controls.
- Review fire alarm standard in main school building.
- Upgrade external lighting in main building.
- Replace intruder alarm system in ASN building.
- Upgrade remaining original heating system and hot and cold water distribution pipes in areas of main school.

Appendix A

Limitations and Exclusions

Introduction

We will not seek to impose any particular limitations upon the survey work beyond those of normal surveying practice.

We will carry out a detailed, non-disruptive, visual inspection of the exposed parts of the building fabric that are readily and safely accessible at the time of our survey, using our standard survey equipment.

Our report will express our opinion on the condition and standard of construction of the inspected parts of the property and recommend further investigation or repair where necessary.

The survey will be limited to the subject property and no responsibility will be accepted for any defects that might materially affect the property, which are out with the scope of the survey.

Health and Safety

The inspection will be executed in a fashion in compliance with the Health & Safety at Work, etc Act 1974. Unless otherwise stated, it will be done without the benefit of internal or external scaffolding, guard rails or mechanical hoists. The external inspection will, therefore, be limited to ground level to inspection from accessible opening in the external fabric, or by the use of a 5 metre sectional ladder.

Deleterious Materials

Testing of components or taking of samples will not be taken through our inspection. If the presence of deleterious materials is suspected in the construction of the building, we will recommend further investigations are carried out by the appropriate specialists. Our inspection does not constitute an asbestos survey in accordance with the Control of Asbestos at Work Regulations.

Services

We will carry out a visual inspection of the primary service installations to include electrical and mechanical services where accessible. No tests of existing services will be undertaken at the time of our inspection. If, as a result of inspection and where considered necessary, we will advise if further investigations and reports should be obtained by independent specialists.

Unless agreed beforehand, our inspection will not comment on the suitability of the property for any use and the client is, therefore, advised to ensure that their use is possible and all processes, trades and activities are viable and permitted. No enquiries will be made to any local or statutory authority regarding any form of "Notice" that might have been served on the property at any time in the past or present. Similarly our report excludes any investigation into the structural design and suitability and compliance with legislation relating to buildings.

Environmental Conditions

The scope of the survey will be limited by the particular weather conditions pertaining at the time of inspection and no guarantee will be given with regard to the performance of the elements of the building during different conditions.

Where existing, the external inspections will be limited by the presence of any coverings of vegetation and no stripping off of the vegetation, including ivy, trellises, etc will be undertaken.

Contamination and Pollution

We will not make enquiries or investigations as to whether the property or any part of it or any neighbouring property appears on any register of contaminated land or might be contaminated or otherwise affected within the scope of the Environmental Protection Act 1990 or other legislation. We will, therefore, be unable to report that the property is free from risk in this respect. For the purpose of our report we will assume that such enquiries would reveal nothing which would affect the terms of our report.

Confidentiality and Use.

Our report is for the sole use of Moray Council and is confidential to the Council and their Professional Advisors. It should not be reproduced in whole or in part or relied upon by a Third Party for any purpose without the express prior written consent of Moray Council.

It should be understood that the report must not be used as any form of specification. Prior to the selection of an appropriate specification, it is likely that further investigation and exploratory works will be required following on from the survey in order to determine the full extent of the specification works necessary prior to submission to contractors for pricing.

Appendix B

Record Photographs


Roofs



1. Old school central timber trusses



2. Trusses resting on stools



3. Concrete beam roof to two storey building



4. Decking below concrete slab roofs



5.



6. Steel roof joists to ASN building



7. Natural slate to old building



8. Slipped and broken slates



9.



10.



11. Single ply membrane



12. SPM to two storey building



13.



14. Standing seam to New Nursery



15. Copper to dormer roofs



16. Debris on flat roofs



17.



18. Skylights to old hall



19.




20.



21.



22. Georgian wired glass



23. Domed GRP rooflights



24.



25. PVC cupola above Kitchen



26.




27. Cast iron ogee gutters



28. Half round cast iron to perimeter



29. Vegetation in gutters



30. UPVC ogee gutters to ASN building



31. SPM valley gutters



32. Part blocked gutter to New Nursery



33. Cast iron hopper heads and downpipes



34. UPVC downpipes



35. Cast iron soil vent pipes



36. Water tank tower and boiler chimney

External Walls



37. Brickwork external walls



38. Natural stone external walls



39. Concrete framed masonry walls



40. Concrete framed external walls



41. Composite panels to ASN building



42. Ventilation below timber floors



43. Ventilation to stone building



44. Ground level close to DPC



45. Plywood screening below ASN building



46. Brick walls to New Nursery



47. Brickwork to external store



48. Damaged brickwork



49. Stone walls to old building




50. Spalling roughcast



51.



52. Composite panels to ASN building




53. Timber entrance doors



54. Timber glazed fire exits



55. Timber doors



56. Single timber fire exit doors



57. Steel single doors




58. Powder coated aluminium doors



59.



60. Powder coated patio doors



61. Timber windows



62. Rotten timber window frames



63.



64.



64. UPVC windows to ASN building



65. UPVC windows to school building



66.



67. Glazing seals failing



68. UPVC windows internally



69. Steel centre pivot window



70. Aluminium windows to New Nursery



71. Double glazing




72. Blown double glazing units



73. Lockable lever handles



74. Cantilever top hung window ironmongery



75. Window hinge mechanism

External Decoration




76. Rainwater goods



77.



78. Timber guardrails and fencing



79. Metal gates

Steps and Ramps




80. Concrete ramps



81.



82. Timber ramps (ASN building)



83. Concrete steps to Room 12



84. Timber steps (ASN building)



85. Concrete steps to Boiler House




86. Metal tubular guard rail



87. Galvanised guard rail



88. Timber guard rail



89. Wet rot in timber posts

Floors



90. Concrete beam floors



91. Beam & block floors



82. Sheet vinyl flooring to corridors



83. Sheet vinyl flooring to classrooms



84. Sheet vinyl flooring to toilets



85. Tape repairs to vinyl



86. Open joints in vinyl flooring



87.



88. Surface damage to vinyl flooring



89. Vinyl tiles



90.



91.



92. Damaged carpet flooring



93.



94. Soiled and worn carpets



95. Terrazzo flooring



96. Cracked Terrazzo flooring



97. Timber boarding (Stage)



98.



99. Timber boarding to cupboards



100. Painted concrete floors



101.



102. Concrete stairs




103. Terrazzo treads and risers



104. Vinyl treads and risers




105. Timber stairs (Stage)



106. PVC coated handrails



107. Tubular metal handrails



108. Metal balustrades

Ceilings



109. Suspended ceiling tiles



110.



111. Watermarked ceiling tiles



112.



113. Plaster/plasterboard ceilings



114.




115. Cracked and spalling plaster



116.



117. Previous repairs to cracks



118.



119. Fibre tiles



120.



121. Watermarked fibre tiles



122. Beam & block ceilings




123.



124. Composite panel ceilings (ASN)

Internal Walls



125. Brick and block walls



126. Plastered walls



127. Plastered walls with curved top



128. Damage to plastered walls



129. Cracked plaster walls



130.



131.



132. Failed taped joints to plasterboard



133. Plasterboard walls with no decoration



134. Timber linings



135. Wetwall



136.



137.



138. Ceramic tiles




139.



140. Borrowed lights



141.



142. Timber hollow core doors



143. Timber hollow core cupboard doors



144. Double timber fire doors



145. Timber double doors



146. Corridor doors



147. Veneered doors



148.



149. Georgian wired glass



150. Brass ironmongery



151.



152.



153. Chrome ironmongery



154. Missing ironmongery



155. Aluminium ironmongery



156. Metal rim locks

Sanitary Ware



157. Urinals




158.



159. Stainless steel urinal troughs



160.



161. Typical WC



162.



163. PVC vanity basin



164. China vanity basin



165. Vanity basin



166. Stainless steel inset basin



167. Wall hung basins (various)



168. Pedestal basins



169. Composite trough basins



170. Copper and PVC waste pipes



171. PVC shower tray



172. Accessible toilets



173. Composite cubical partitions



174. Dated cubical partitions



175. Damaged cubical partitions



176. Vanity units



177. Damaged vanity units



178.



179. Commercial kitchen



180. Stainless steel kitchen sinks



181. Stainless steel inset sinks



182. Dated stainless steel inset sinks



183. Cleaners butler sinks




184. PVC waste pipes

Internal Decoration



185. Water marked plaster/plasterboard ceilings



186. Timber linings to ceilings



187. Watermarked fibre tiles



188. Paint peeling from plastered walls



189.



190.



191. Paint chipped and peeling on joinery items

Furniture



192. Classroom tables and chairs



193.



194. Sink base units



195. Misaligned doors



196. Dated sink base units



197. Damaged sink base units



198.



199. Staffroom furniture



200.

Mechanical and Electrical Photographs



201. Boilers – Plant room 0/71



202. Control panel – heating. 0/71



203. Pressurisation unit – heating – 0/71



204. Pipework – heating system. 0/71



205. Wet convector – main school. 1/33



206. Radiator – cast iron. Non upgraded part of main school



207. Radiator – main school 1/6 upgraded.



208. Radiator – LST type. Nursery extension GO5



209. Electric convector – ASN building.



210. Electric convector with guard. ASN building.



211. Calorifier – hot water storage. Main school 0/71



212. Pipework – hot and cold new. Main school 1/39



213. Pipework – hot and cold existing. Main school 1/63



214. Hot water tank and pipework. Nursery GO2 utility.




215. Point of use hot water storage unit. ASN building



216. Pipework – hot and cold in ASN building typical.



217. Pipework – hot and cold and heating main school service duct.



218. Pipework – existing hot and cold in main school.



219. Gas pipe supply to plant room 0/71 in service duct under main school floor.



220. Gas pipe – supply to plant room under main school floor.



221. Extract fan 1/17 boys toilets main school



222. Extract fan above cookers main school kitchen1/44



223. Extract fan ASN building typical 1-67 toilets



224. Extract fan nursery – Utility GO2 room



225. Heat recovery ventilation unit. Nursery toilets G05



226. Heat recovery unit. Serves nursery kitchen area



227. Air conditioning indoor unit. Main school kitchen 1/44



228. Air conditioning outdoor unit main school kitchen 1/44



229. Distribution board main school 1/3 typical.



230. Main switch for canteen. Main school 1/3



231. Distribution board main school 1/60



232. Distribution board main school 1/3



233. Distribution board nursery utility room GO5



234. Distribution board – Nursery utility room GO5



235. Distribution board – ASN building 1/79



236. Consumer unit / RCD protection ASN building typical.



237. Sockets main school typical



238. Sockets and dado trunking nursery typical.



239. General wiring – ASN building ceiling space.



240. General and controls wiring main school 0/71




241. LV cabling – 1/3 meter cupboard main school



242. LV cabling – cleaners 1/39 main school



243. Lighting – main school toilets and corridors typical



244. Lighting – main school classroom typical




245. Lighting main school dining hall 1/41



246. Lighting main school hall 1/33




247. Lighting main school class typical



248. Lighting – nursery extension entrance



249. Lighting – nursery large room GO9




250. Lighting – nursery toilets GO5




251. Lighting ASN building typical classroom




252. Lighting – ASN corridors typical




253. Lighting controls main school typical



254. Lighting control ASN building typical



255. Emergency lighting – main school typical at exits.



256. Emergency exit lighting main school typical.



257. Emergency lighting ASN building typical exit.



258. Emergency lighting (maintained) nursery.



259. Emergency lighting main school hall



260. External emergency light main school entrance



261. External lighting main school example



262. External lighting – ASN building example




263. External lighting – nursery extension.



264. External lighting main school




265. Fire alarm control panel main school 1/1



266. Fire alarm control panel ASN building



267. Fire system detection head – main school and ASN building typical



268. Fire system – call point main school and ASN building typical



269. Fire detection system – strobe device typical.



270. Fire alarm system wiring – typical.



271. Period bell controller – main school



272. Period bell typical main school and nursery extension



273. Disabled alarm system remote indicator. Main school reception office



274. Disabled alarm system pull chord activation. ASN building – typical.



275. Induction loop system. Nursery extension




276. Intruder alarm keypad main school room 1/2



277. Intruder alarm keypad – Nursery extension.



278. Intruder alarm PIR main school typical.



279. Door access unit – nursery entrance from school.



280. Door access control handset – nursery.



281. Door access intercom – Main school reception for internal entrance door.



282. Door access fob reader – ASN building main entrance.



283. CCTV external camera main school entrance.



284. CCTV monitor and recorder main school 1/2



285. Electric window opening motors main school 1/41



286. Electric window controls main school 1/41



287. Cold water supply pipework ASN building.



288. Pipework – heating system.



289. Pipework – new heating system.



290. New heating pipework under school floor.

External Areas



291. Rear tarmacadam car park



292. Tarmacadam playground



293. Playground furniture



294. Tarmacadam footpaths



295. Paving slab footpaths



296. Damaged paving slabs



297. Timber post and rail fencing



298. Security mesh fencing



299. Metal bar fencing



300.



301. High security mesh to playing field



302. Metal chain link fencing



303. Galvanised fencing



304. Concrete post and chain link



305. Timber boarded fencing



306. Timber boarded gate



307. Timber double gates to playing field



308. Metal bar gates



309. Vehicle metal bar gates



310. Metal framed security gates



311. Natural stone walls



312. School signage



313. Playground drainage



314. Blocked drainage



315. Blocked, flooded drainage



316. Playground shelter



317. Spalling concrete structure



318. Galvanised framed bike shelters



319.



320. Timber sheds