

# **Summary Building Condition Survey Report**

of

# Aberlour Primary School Mary Avenue, Aberlour AB38 9PN

9<sup>th</sup> February 2024



# **CONTENTS**

- 01 Introduction
- 02 Property Description and Methodology
- 03 Summary of Condition / Key Issues
- 04 Conclusion

## **Appendices:**

- A Limitations and Exclusions
- **B** Photographic Schedule

#### 1. Introduction

- 1.1. This report has been prepared by Andrew Clark MRICS, MCIOB and Neal Stewart Building Services Engineer, of Moray Council. The report is confidential to Moray Council and is not intended for public release without Moray Council's express approval. The report summarises the condition of the property condition at the time of the survey, periodic reviews of material condition will be required. An inspection of the property was undertaken on Friday 9<sup>th</sup> February 2024.
- 1.2. The report seeks to provide a brief summary of the condition of repair, identifying the principal defects and wants of repair, together with the main points of concern arising from the inspection. Items of a routine or minor maintenance nature have generally not been listed.
- 1.3. At the time of our inspection, the weather conditions were windy and freezing with snow showers.
- 1.4. The premises comprise a primary school, constructed in a single storey with single storey outbuildings. The original school building was constructed circa 1897, extended in 1970 with further extensions in 2002 and 2023. The original part of the main school building is Category "B" Listed.
- 1.5. The property was occupied during our inspection which was thus limited by the nature and extent of fixtures and fittings and of decorative finishes. In particular, the existence of fitted floor finishings throughout limited any inspection of the underlying floor structure. Framing out of walls and plasterboard linings conceal the underlying structure and it is possible that defects relating to moisture ingress may exist which are not revealed internally. Please also note and consider the Limitations and Exclusions Section, which is appended to this report.
- 1.6. Pitched roofs were examined from ground level with the use of binoculars and with a drone. Accessible flat roofs were examined from a standard 3.80m ladder and with the use of a drone. Access was provided to all internal areas with the exception of the store rooms 1/9a, 1/31 and the external stores.
- 1.7. All mechanical and electrical building services were inspected as far as reasonably practical. Domestic water supply pipework, heating pipework, alarm systems cabling and small power systems cabling was in most cases concealed in internal walls or under floor spaces and not reasonably practical to inspect. An effort has been made to assess the age and likely condition of these elements by using historic data, where available, to pinpoint the likely age of materials.
- 1.8. Extract and supply fan ventilation systems were tested by switching on and observing operation only. A detailed inspection of fan units, ductwork or controls has not been carried out during the non-intrusive survey.
- 1.9. Fire and intruder alarm systems were visually inspected for condition and age as far as reasonably practical and no physical testing was carried out on these services during the survey.

#### 2. Property Description and Methodology

- 2.1 The property comprises of single storey buildings with pitched and flat roofs.
- 2.2 The subjects are of natural stone, masonry and timber framed construction. Roofs are covered with natural slate and metal profile roofing to pitched roofs and mineral felt, GRP, lead and single ply membrane to flat roofs. Rainwater goods are half round and ogee cast iron gutters with hopper heads, UPVC gutters, cast iron and UPVC downpipes. External walls are of natural stone, masonry with roughcast finish, timber linings, metal profile and metal plank construction. Floors comprise concrete slab and suspended timber. Windows are UPVC, powder coated and timber sliding sash with single and double glazed units. External doors are timber (including "Listed"), PVC and powder coated.

Internally, ceilings are a combination of lath & plaster, plasterboard and suspended ceiling tiles, walls are plaster, plasterboard, timber panelling, blockwork and Wetwall. Floor coverings comprise carpet, carpet tiles, sheet vinyl, linoleum, decorative ceramic tile, timber parquet flooring, timber boards and concrete slab. Internal doors are generally timber panelled, solid core and hollow core some with glazed panels. Ironmongery comprises bakelite knobs and aluminium lever handles.

The heating system comprises 2 floor standing oil fired boilers and basic, dated controls. LTHW generated is pumped through partly insulated steel pipework, to mostly cast iron radiators throughout the building. A small number of steel panel and electric convector heaters supplement the heating system. The enhanced provision area of the school has underfloor heating, also supplied by the 2 oil boilers. The recently refurbished nursery area of the school has electrical convectors and also roof and wall mounted electrical radiant panels.

Hot water is generated by the oil boilers and stored and distributed to areas of the school by the 2 main calorifiers, situated in the kitchen store cupboard and the attic space above the corridor to the enhanced provision zone. A number of hot water storage tanks and electric point of use storage heaters are also installed throughout the building providing hot water to outlets. The recent nursery refurbishment and extension in 2023 incorporates electrical instantaneous point of use water heaters.

Cold water is supplied to building outlets via partly insulated copper pipework. 4 cold water storage tanks are located within attic spaces of the building. These supply cold water to building outlets and also hot water calorifiers. A recent refurbishment of the nursery zone has seen the cold water storage tank removed from the attic space above 1/27 classroom and the rooms within the nursery area are now direct mains fed, with no storage tanks.

A modern plastic double skinned oil storage tank is located externally, positioned within a metal mesh style, locked enclosure. Oil supply pipework is a mix of copper and steel and controls are dated.

Mechanical ventilation is provided throughout the building by means of varying sizes of electrical extract fans. These are generally located in toilets, kitchenettes and other rooms. A number of these fans are enabled by motion sense controls, while others are local on/off switch only.

The recent refurbishment to the nursery zone of the school has seen new lo carbon extract fans installed in almost all rooms.

A roof mounted large extract fan is installed above the kitchen. This fan removes cooking vapours and odours from the cooking appliances in the kitchen. A Local control unit enables on/off and speed control.

The Electrical installation comprises incoming supply cable, main distribution board and sub distribution boards located in electrical cupboard in 1/5c corridor. Further distribution boards are located in the kitchen, nursery zone and the enhanced provision zone of the building. General wiring appears to be PVC sheathed twin and earth mainly, however some evidence of existing mineral insulated, copper clad cabling was evident in roof spaces. Wiring accessories are mainly white plastic, however, some metal clad wiring accessories were also noted in some rooms.

The internal lighting system generally, is a mix of T5 and T8 fluorescent tube style light fittings. Some local replacement LED fittings are also installed. Lighting is generally enabled by local switches, although some areas are controlled via absence control sensors. A number of external lights are installed around the outside walls of the building. These are controlled by a time clock located within the school.

Internal emergency lighting is a combination of ceiling and wall mounted LED bulkhead fittings and micro LED spots and variations of the general light fittings. Some external light fittings also have self-contained emergency lighting provision.


A modern smoke detection and alarm system is installed throughout, with addressable control panel, field devices and connecting wiring being apparent in almost all rooms and circulation spaces.

A basic CCTV system is installed with 1 fixed camera located at the main entrance. It was not clear at the time of the survey where the footage from this camera was saved or viewable and if the system was functioning.

At the recent nursery refurbishment a modern CCTV camera has been installed in classroom 1/27. It is presumed that this system is wireless and is accessible and viewable through an application on a desktop computer or mobile device.

Automatic security door access systems are installed to the corridor doors to the enhanced provision zone, main entrance internal door (intercom) and to the main door of the recently refurbished and extended nursery zone. (fob and card reader system).

- 2.3 Building size The properties GIFA is 1553m2.
- 2.4 Condition codes and priority categories.



Performing well and operating efficiently
Performing adequately but showing minor deterioration
Showing major defects and/or not operating adequately
Life expired and/or serious risk of imminent failure
Not applicable for assessment

#### PRIORITY RATING MATRIX

- 1 Must Do (immediate) to address essential H&S/comply with law/avoid service disruption.
- 2 | Should Do (within years 1 and 2) to achieve/maintain basic standards.
- 3 Would Do (within years 3 to 5) desirable works if affordable.
- 4 **Programmed (within years 6 to 25)** consider within Planned Maintenance.

### 3. Summary of Principal Considerations

#### 3.1 Primary School Building

- Slates slipped and missing.
- GRP roofs are blistered, not draining and ponding.
- Felt roof to boiler house leaking at the perimeter.
- Metal profile roofs have significant cut edge corrosion.
- Several chimneys have open pots, not capped or vented.
- Cast iron gutters and downpipes are part blocked and leaking.
- Roughcast walls are cracked and spalling.
- Timber windows have isolated rot.
- UPVC window seals are failing.
- Powder coated windows have missing ironmongery.
- Ramp to side has cracked and spalling render.
- External decoration is overdue.
- Lath and plaster ceilings are cracked.
- Plasterboard walls are damaged in isolated areas.
- Timber panelled doors are damaged and a poor fit.
- Carpets are soiled and worn.
- Sanitary ware is dated and cracked.
- Toilet cubicles are very dated with several previous repairs.
- Internal decoration is overdue.

#### 3.2 Mechanical and Electrical Installations

- There is only 1 camera field of a CCTV system covering the school building.
- There is no intruder alarm installed in the building.
- A large percentage of the lighting is fluorescent tube type.
- The boilers and heating system have exceeded their recommended life.
- The cold water pipework in the main school has exceeded its recommended life.
- The hot water pipework in the main school has exceeded its recommended life.
- The main entrance doors to the school have no automated security access system.

#### 3.3 External Areas

- Tarmacadam car park has surface erosion and potholes.
- Tarmacadam footpaths are cracked and raised by tree roots.
- Concrete panel fence has cracked posts and panels.
- Timber gates have extensive timber rot.
- Metal gates are a poor fit and require significant easing and adjusting.
- Stone walls are eroded and require repointing.
- External stores have rotten timber lintols.

## 4 Conclusion

#### 4.1 A brief summary of the elements condition.

Element	Condition	Priority
Roofs	D	2
Floors & Stairs	С	3
Ceilings	В	4
Ext. Walls, Windows & Doors	С	3
Internal Walls & Doors	С	3
Sanitary Services	С	2
Mechanical	С	2
Electrical	В	4
Decoration	С	3
Fixed Int. Facilities	В	4
External Areas	С	3
Outdoor Sports Facilities	N/A	

This information must be transferred to the Master Core Fact Sheet.

#### 4.2 Improvements Recommended

To prevent or reduce, vandalism / damage / accelerated deterioration.

- Install a comprehensive field of CCTV.
- Install an intruder alarm system.
- Install automated security door access systems to all external doors.
- Upgrade internal lighting to LED.
- Upgrade heating system and heat source.

#### Appendix A

#### **Limitations and Exclusions**

#### Introduction

We will not seek to impose any particular limitations upon the survey work beyond those of normal surveying practice.

We will carry out a detailed, non-disruptive, visual inspection of the exposed parts of the building fabric that are readily and safely accessible at the time of our survey, using our standard survey equipment.

Our report will express our opinion on the condition and standard of construction of the inspected parts of the property and recommend further investigation or repair where necessary.

The survey will be limited to the subject property and no responsibility will be accepted for any defects that might materially affect the property, which are out with the scope of the survey.

#### **Health and Safety**

The inspection will be executed in a fashion in compliance with the Health & Safety at Work, etc Act 1974. Unless otherwise stated, it will be done without the benefit of internal or external scaffolding, guard rails or mechanical hoists. The external inspection will, therefore, be limited to ground level to inspection from accessible opening in the external fabric, or by the use of a 5 metre sectional ladder.

#### **Deleterious Materials**

Testing of components or taking of samples will not be taken through our inspection. If the presence of deleterious materials is suspected in the construction of the building, we will recommend further investigations are carried out by the appropriate specialists. Our inspection does not constitute an asbestos survey in accordance with the Control of Asbestos at Work Regulations.

#### **Services**

We will carry out a visual inspection of the primary service installations to include electrical and mechanical services where accessible. No tests of existing services will be undertaken at the time of our inspection. If, as a result of inspection and where considered necessary, we will advise if further investigations and reports should be obtained by independent specialists.

Unless agreed beforehand, our inspection will not comment on the suitability of the property for any use and the client is, therefore, advised to ensure that their use is possible and all processes, trades and activities are viable and permitted. No enquiries will be made to any local or statutory authority regarding any form of "Notice" that might have been served on the property at any time in the past or present. Similarly our report excludes any investigation into the structural design and suitability and compliance with legislation relating to buildings.

#### **Environmental Conditions**

The scope of the survey will be limited by the particular weather conditions pertaining at the time of inspection and no guarantee will be given with regard to the performance of the elements of the building during different conditions.

Where existing, the external inspections will be limited by the presence of any coverings of vegetation and no stripping off of the vegetation, including ivy, trellises, etc will be undertaken.

#### **Contamination and Pollution**

We will not make enquiries or investigations as to whether the property or any part of it or any neighbouring property appears on any register of contaminated land or might be contaminated or otherwise affected within the scope of the Environmental Protection Act 1990 or other legislation. We will, therefore, be unable to report that the property is free from risk in this respect. For the purpose of our report we will assume that such enquiries would reveal nothing which would affect the terms of our report.

#### Confidentiality and Use.

Our report is for the sole use of Moray Council and is confidential to the Council and their Professional Advisors. It should not be reproduced in whole or in part or relied upon by a Third Party for any purpose without the express prior written consent of Moray Council.

It should be understood that the report must not be used as any form of specification. Prior to the selection of an appropriate specification, it is likely that further investigation and exploratory works will be required following on from the survey in order to determine the full extent of the specification works necessary prior to submission to contractors for pricing.

# Appendix B

# **Record Photographs**

# Roofs



1. Overview of roofs



2. Timber roof structure



3. Timber sarking boards



4. Timber roof structure above Nursery



5. Timber roof structure above ASN



6. Plywood sarking



7. Metal roof structure above ASN corridor



8. Metal cladding to ASN corridor



9. Concrete roof slab over Boiler House



10. Slipped and broken slates



11. 12.







13. 14. Metal profile roof above ASN corridor





15. Cut edge corrosion





17. Mineral felt and gravel roof covering



18. Rainwater penetration at perimeter



19. Lead roof above entrance



20. Lead roof above dormer window



21. SPM to new Nursery extension



22. GRP roof above Library - ponding



23. GRP roof above toilets



24. Roof cleaning required



25. Metal skylights



26. Metal skylights and broken slate



27. New skylight above Nursery



28.



29. Mineral fibre insulation above ceilings



30. Areas of missing insulation





31. 32. Ogee cast iron gutters





33. 34. Half round cast iron gutters





35. UPVC gutters

36. Isolated repairs required



37. Metal box gutters



38. Flat roof outlets



39. Cast iron hopper heads



40. Cast iron downpipes




41. UPVC downpipes



42. Leaking gutters



43. Blocked rainwater downpipes



44. Stone chimneys



45. Stone boiler flue



46. Redundant (capped) chimneys



47. Chimney pots not capped or vented

# **External Walls**



48. Natural stone walls



49. Masonry walls



50. Steel framed walls to ASN corridor



51. Evidence of leaks/condensation at base of steel frame



52. Masonry/timber framed outbuildings



53. Rot in timber lintols



54. Natural stone walls



55. Fyfe stone feature walls



56. Roughcast walls



57.



58. Spalling roughcast



59. Cracked roughcast



60. Cracks at previous repairs



61. Timber cladding to ASN



62.



63. Metal plank cladding to new Nursery extension



64.



65. Timber panelled external doors



66. Timber door to Boiler House



67. Timber ledged & braced doors - outbuildings



68.



69. Powder coated doors – new Nursery



70.



71. Timber panelled double doors



72. Wet rot in door frames



73. Timber fire escape doors



74. PVC double doors



75. Powder coated double doors



76. Georgian wired glazing



77. UPVC small windows





78. UPVC medium windows

79.



80. UPVC large windows



81. Timber sliding sash windows



82. Wet rot in window frames



83. Timber sliding sash windows





84. 85. Powder coated windows



86. Poor fit with missing ironmongery



87. Powder coated windows to new Nursery extension











90. 91. Isolated blown double glazed units



92. Typical lever handles



93. Ring pulls on sliding sash windows



94. Latches on sliding sash windows



95. Lockable lever handles

# **External Decoration**



96. Painted cast iron and metal rainwater goods



97. Stained timber linings



98. Timber external doors



99. Painted timber and metal fences and gates

## **Steps and Ramps**



100. Concrete steps to entrances



101. Concrete steps to Boiler House



102. Damage to nosings



103. Concrete ramps



104.



105. Spalling render to side ramp



106. New steps to ASN fire escape



107. Metal guard rail to main entrance





108. Galvanised tubular guard rail

109.

## **Floors**





110. Concrete floor slab

111. Soiled carpet tiles





112. Worn carpet

113. Sheet vinyl



114. Some open joints in sheet vinyl



115. Timber parquet flooring



116. Open joints



117.



118. Decorative tile at front entrance



119. Painted concrete floor – Boiler House

# **Ceilings**



120. Suspended ceiling tiles - main school



121. Suspended tiles - Nursery



122. Suspended tiles - Kitchen



123. Plasterboard ceilings



124. Water damaged plasterboard ceilings



125.



126. Cracked plastered ceilings



127. Lath & plaster ceilings



128. Damage to lath & plaster



129. Underside of metal profile roof



130. Concrete ceiling – Boiler House

# **Internal Walls**



131. Timber stud partitions



132. Plasterboard walls



133. Damage to plasterboard



134.



135. Lath & plaster walls



136. Damage to lath & plaster



137. Painted blockwork walls



138. Timber linings at low level



139.



140. Timber panelling at low level



141. Composite panelling in pupil toilets



142.



143. Ceramic tiles



144. Timber panelled doors



145. Timber panelled classroom doors



146. Timber flush doors



147. Veneered hallow core doors



148. Veneered solid core doors



149. Veneered solid core doors



150. PVC faced timber doors



151. Aluminium doors



152.



153. Timber cubicle doors – pupil toilets



154. Timber double doors





155. 156.



157. PVC borrowed lights – Dining room



158. Timber borrowed lights - Library



159. Broken glass



160. Timber borrowed lights - Nursery



161. Georgian wired glass in doors



162. Pyro glass in corridor fire doors



163. Bakelite door knobs



164. Aluminium lever handles



165. Stainless steel lever handles

# Sanitary Ware



166. Wall hung china urinals



167. PVC cistern



168.



169. Typical W.C.



170. Crazed porcelain



171. Staff W.C.





172. Pupil W.C.

173.






174. New pupil toilets in Nursery

175.







177. China vanity basin



178. Typical wall hung basin



179. Pupil wall hung basin



180. Isolated cracking of basins



181. New vanity basin in ASN



182. Taps vary considerably



183. Motion sensor taps in Nursery



184. Sheet vinyl shower trays



185. PVC waste pipes



186. Copper waste pipes in pupil toilets



187. Lead waste pipe in staff toilet



188. Damaged lead pipe at floor level



189. Typical accessible toilet



190. Cubical partitions – Staff toilets



191. Vanity base unit



192. Commercial kitchen



193. Dated stainless steel sinks









196. Modern stainless steel sinks - Nursery



197. Modern sinks in ASN



198. Stainless steel inset sinks



199. Butler sink



200. PVC waste pipes

## **Internal Decoration**



201. Marked ceilings



202. Peeling paint to walls



203. Soiled painted doors



204. Chipped paint to doors



205. Scratched door surfaces



206. Chipped and peeling joinery items

## **Furniture**






207. Tables and chairs

208.







210. Modern kitchen units - Nursery



211. Staff room furniture



212.

### **Mechanical and Electrical Photographs**



213. Oil fired boilers.



214. Heating control panel – boiler house.



215. Radiator – cast iron column – boys toilets.



216. Heating system pipework typical.



217. Wet convector heater – hall.



218. Electric convector – nursery refurbishment.



219. Hot water storage calorifier kitchen cupboard



220. Hot water storage calorifier - attic above 1/30



221. Point of use water heater – staff toilet.



222. Point of use water heater boys toilets.



223. Point of use water heater – staff room.



224. Pipework – hot and cold boys toilets.



225. Cold water storage tanks 1 and 2.



226. Cold water storage tank above 1/30 corridor.



227. Cold water storage tank 05 – kitchen attic space.



228. Pipework hot and cold – kitchen store.



229. Extract fan – wall mounted hygiene room 1/33



230. Extract fan ceiling mounted – staff toilet.



231. Extract fan / ductwork filters main kitchen.



232. Extract canopy - main kitchen.



233. Main electrical distribution board – corridor 1/5c



234. Distribution board – kitchen.



235. Distributionm board – nursery refurbishment.



236. Consumer unit – sensory room 1-39



237. Sockets typical room 1/37



238. Switches - lights. Typical



239. Incoming electrical supply – corridor 1/5c cupboard



240. Switchgear - corridor 1/5c



241. Lighting – staff room



242. Lighting – main hall



243. Lighting classroom 1/35



244. Lighting – corridor



245. Lighting – kitchen.



246. Lighting – nursery office refurb 2023



247. Emergency exit lighting typical.



248. Emergency exit spot light LED – nursery.



249. External lighting main school typical.



250. External LED lighting nursery refurb 2023



251. Fire alarm system control panel 1/1 lobby.



252. Fire alarm call point – corridor escape door.



253. Smoke detector head – boilerhouse.



254. Fire alarm strobe – nursery extension refurb 2023.



255. Door access system - 1/30 corridor



256. Door access intercom – main entrance internal door



257. Door access system - 1/30 corridor



258. Door access system emergency release – typical.




259. Person hoist system – hygiene room 1/33



260. Hoist system - room 1/40

## **External Works**







262. Potholes

264.



263.





265. Overview of playground



266. Tarmacadam front playground



267. Previous patches and ponding



268. Tarmacadam rear playground



269. Cracks and previous patches



270. Playground equipment



271. Playground equipment in poor condition



272. Concrete paths



273. Tarmacadam paths



274. Cracked tarmacadam



275. Tarmacadam damaged by tree roots



276. Concrete steps



277. Timber boarded fence 1.80m



278. Timber boarded fence 0.90m





279. 280. Security mesh fencing





281. 282. Metal rail fencing





283. Metal railings to front boundary

284.



285. Metal railings to Boiler House



286. Timber boarded gates



287.



288. Wet rot in timber gates



289.



290.



291. Galvanised bar double gate



292. Security mesh gate



293. Metal mesh single gate



294. Metal mesh double gate



295. Metal rail gate



296. Stone walls to the perimeter



297. Erosion of pointing



298. Spalling pointing



299. Cracks to stone walls



300. Concrete post and panel wall



301. Cracked concrete panels



302. Cracked concrete posts






303. School signage

304.







306. Part blocked surface water gullies









309. Pupil shelter

310. Nursery shelter



311. Metal cycle hoops



312. Stainless steel cycle hoops



313. Cycle lock ups



314. Metal sheds





315. Polytunnel

316. Oil tank enclosure





318. Grass sports field

317. Outbuildings