

# **Summary Building Condition Survey Report**

of

# Knockando Primary School Knockando, Ballindalloch AB38 7RY

11<sup>th</sup> and 12<sup>th</sup> June 2024



Z00488 / ADC & NS

# **CONTENTS**

- 01 Introduction
- 02 Property Description and Methodology
- 03 Summary of Condition / Key Issues
- 04 Conclusion

## **Appendices:**

- A Limitations and Exclusions
- **B** Photographic Schedule

### 1. Introduction

- 1.1. This report has been prepared by Andrew Clark MRICS, MCIOB and Neal Stewart Building Services Engineer, of Moray Council. The report is confidential to Moray Council and is not intended for public release without Moray Council's express approval. The report summarises the condition of the property condition at the time of the survey, periodic reviews of material condition will be required. An inspection of the property was undertaken on Tuesday 11<sup>th</sup> and Wednesday 12<sup>th</sup> June 2024.
- 1.2. The report seeks to provide a brief summary of the condition of repair, identifying the principal defects and wants of repair, together with the main points of concern arising from the inspection. Items of a routine or minor maintenance nature have generally not been listed.
- 1.3. At the time of our inspection, the weather conditions were cool and windy with rain showers.
- 1.4. The premises comprise a school, games hall and dining block, all constructed in single storey with single outbuildings. The school was constructed circa 1900, the games hall (HORSA hut) was constructed circa 1950 and the dining block was constructed circa 1970.
- 1.5. The property was occupied during our inspection which was thus limited by the nature and extent of fixtures and fittings and of decorative finishes. In particular, the existence of fitted floor finishings throughout limited any inspection of the underlying floor structure. Framing out of walls and plasterboard linings conceal the underlying structure and it is possible that defects relating to moisture ingress may exist which are not revealed internally. Please also note and consider the Limitations and Exclusions Section, which is appended to this report.
- 1.6. Pitched roofs were examined from ground level with the use of binoculars and a drone. Accessible flat roofs were examined from a standard 3.80m ladder and with the use of a drone. Access was provided to all internal areas with the exception of the roof spaces above the north extension and the east classroom.
- 1.7. All mechanical and electrical building services were inspected as far as reasonably practical. Domestic water supply pipework, heating pipework, alarm systems cabling and small power systems cabling was in most cases concealed in internal walls or under floor spaces and not reasonably practical to inspect. An effort has been made to assess the age and likely condition of these elements by using historic data, where available, to pinpoint the likely age of materials.
- 1.8. Extract and supply fan ventilation systems were tested by switching on and observing operation only. A detailed inspection of fan units, ductwork or controls has not been carried out during the non-intrusive survey.
- 1.9. Fire and intruder alarm systems were visually inspected for condition and age as far as reasonably practical and no physical testing was carried out on these services during the survey.

## 2. Property Description and Methodology

- 2.1 The property comprises of three single storey buildings with pitched and flat roofs.
- The subjects are of masonry construction (school), concrete framed construction (games hall/HORSA hut) and timber framed construction (dining block). Roofs are covered with natural slate and "Decra" roof sheets (school) with tree stone chimneys; corrugated asbestos sheets (games hall/HORSA hut); and mineral felt (dining block) to pitched roofs and GRP to the flat roof of the school. Rainwater goods are half round cast iron to the school and dining block with asbestos half round gutters to the games hall/HORSA hut. External walls are of natural stone, some with a roughcast finish, to the school; brick with a roughcast finish to the games hall/HORSA hut; and timber linings to the dining block. Floors comprise concrete slab and suspended timber to the school; concrete slab to the games hall/HORSA hut and suspended timber to the dining block. Windows are aluminium/powder coated metal and upvc with double glazing, to the school; aluminium and metal "Crittall" with single glazing to the games hall/HORSA hut; timber and upvc with single and double glazing to the dining block. External doors are timber, some with Georgian wired glass.

School building internally, - ceilings are a combination of painted plasterboard and suspended ceiling tiles, walls are painted lath and plaster, painted plaster, painted plasterboard and timber linings at low level. Floor coverings comprise carpet, sheet vinyl, quarry tiles and concrete slab. Internal doors are generally hallow core timber with glazed panels and aluminium ironmongery.

Games Hall internally, - ceilings are painted plasterboard, walls are painted brickwork, painted plasterboard. Floor coverings comprise carpet, vinyl tiles and linoleum. Internal doors are hallow core timber and panelled timber and bakelite ironmongery.

Dining Block internally, - ceilings are painted fibreboard and painted plasterboard, walls are painted fibreboard, painted plasterboard and ceramic tile. Floor coverings comprise timber boards, carpet, sheet vinyl, linoleum and quarry tiles. Internal doors are generally hallow core timber and aluminium ironmongery.

The heating system comprises an oil fired, open flued, cast iron heat exchanger type boiler as the heat source. Heated water is distributed around the main building via steel, insulated pipework. Some of this pipework is uninsulated in areas. Heat emitters in the main school building are steel panel of varying ages with TRVs. A basic, old style control panel and control system provides time and sequence control. The heating system in the gym hall building comprises electrical wall mounted convector and fan convector heaters. Heating in the canteen building is also provided by electrical wall mounted convector and fan convector heaters. Both canteen and gym hall buildings heating systems have independent control from the main school.

Domestic hot water in the main building is generated mainly by the oil fired boiler and then stored and distributed via copper pipework, from an unvented hot water cylinder located in the basement plant room. Areas of distribution pipework are uninsulated.

A number of electrical point of use storage heaters provide local hot water for main building classrooms and main playgroup room.

An electrical direct heated unvented storage cylinder and copper pipework distribution circuit provide domestic hot water in the main kitchen, with further electrical point of use water heaters serving cloakroom in the canteen building.

No hot water systems are installed to the games hall building.

Cold water outlets in main school building and the canteen building are direct feed from the mains supply. Copper distribution pipework is uninsulated in places. No storage tanks are installed in any of the buildings. Gym building has no requirement for installation.

A modern plastic, double skinned oil tank installed in an outdoor metal fenced locked enclosure, has been installed as a replacement in recent years. New oil feed copper sheathed pipework has also been installed to the appliance in the basement plant room.

Mechanical ventilation is provided in the games' hall by 4 electrical wall mounted heat recovery type extract fans. These fans have local on/off controls in the games' hall. Further electrical extract fans are installed in the main kitchen and an inline interlocked fresh air supply to the basement plant room for oil combustion purposes.

Pupil or staff toilets do not incorporate mechanical extract generally.

Electrical installation comprises incoming supply cable(s) main busbar and distribution boards located in the main school reception office cupboard. General wiring is a mix of PVC sheathed and mineral insulated copper clad cabling, either concealed in building fabric or in metal/plastic conduit and trunking. Wiring accessories in the main school are white plastic with some rooms having metal clad back boxes and plates. An independent supply cable feeds the busbar chamber and distribution boards for the gym hall building, located in room 1/30. More modern DBs are installed in the gym hall building. General wiring in the gym appears to all be original micc.

A further independent power supply cable enters the kitchen block 1/15 entrance lobby cupboard. DBs are MCB and fuse type protective devices for circuits. General wiring appears to be original micc. Wiring accessories are plastic flush and surface mounted and some metal clad boxes and plates.

The lighting system in the main school building consists generally of fluorescent tube T5 and T8 batten type light fittings, which are controlled locally by on/off switches.

The games hall and canteen building lighting systems are also mainly fluorescent T5 and T8 battens. Some original pendant style fittings are installed in these buildings with all lights being local controlled by on/off switches.

Emergency LED 3w bulkhead fittings are installed throughout all 3 buildings for emergency lighting systems, with the canteen and games hall buildings having had these systems recently upgraded and installed in 2020.

A modern smoke detection and alarm system is installed throughout all 3 buildings. The main school system appears to be a mix of hard wired and radio wireless link type system, incorporating smoke and heat detectors, call points, control panel and sounders/combined detector sounders.

The canteen and games hall fire alarm circuits have recently been upgraded in 2023. These systems now incorporate call points, smoke and heat detectors. These 2 systems are wireless / radio link type systems that are designed to link with the main fire control panel in the main building.

A modern audio/video capable door entry system has recently been installed at the main school entrance internal door. Handsets are located in the head teachers' office and reception office allowing authorised building personnel to control access to this door.

No intruder alarm system in installed in the property.

A basic CCTV system is installed in the main school building, comprising 1 fixed camera at the main entrance, with DVR and monitor located in the reception office.

2.3 Building size – The properties GIFA is :-

School Building 353m2
Games Hall (HORSA) 95m2
Dining Hall 212m2
Total GIFA 660m2.

2.4 Condition codes and priority categories.

CONDITION SUMMARY MATRIX		
Good - A		
Satisfactory - B		
Poor - C		
Bad - D		
N/A		

Performing well and operating efficiently
Performing adequately but showing minor deterioration
Showing major defects and/or not operating adequately
Life expired and/or serious risk of imminent failure
Not applicable for assessment

#### **PRIORITY RATING MATRIX**

- 1 Must Do (immediate) to address essential H&S/comply with law/avoid service disruption.
- 2 | Should Do (within years 1 and 2) to achieve/maintain basic standards.
- Would Do (within years 3 to 5) desirable works if affordable.
- 4 **Programmed (within years 6 to 25)** consider within Planned Maintenance.

## 3. Summary of Principal Considerations

## 3.1 Primary School Building

- Stone skew stones are eroded and crumbling.
- Two chimney pots are not capped and vented.
- Cast iron gutters are leaking at stop ends and joints.
- External walls and roughcast is cracked to the Boys toilet.
- External decoration is overdue with exposed cast iron and timber elements.
- Suspended ceiling tiles are peeling and in poor condition.
- Internal walls are cracked at the external corners of the Staff Room.
- Ceramic tile splashbacks are in poor condition with previous repairs.
- Suspended timber floors are uneven and require further investigation.
- Sheet vinyl is damaged and lifting in isolated areas.
- Internal decoration is overdue.
- Sink base units are life expired and are collapsing.

## 3.2 Games Hall (HORSA Hut)

- Corrugated asbestos roof is covered with moss and damaged in isolated areas.
- Asbestos gutters are blocked and leaking.
- The concrete frame of the external walls is cracked in isolated areas.
- Crittall windows are in poor condition, broken glass and 75% boarded internally.
- Internal doors and ironmongery are life expired.
- Internal decoration is overdue.

### 3.3 Dining Block

- Felt roofing is life expired with previous repairs.
- Plywood fascia, soffits and gables are rotten and collapsing.
- Cast iron gutters are leaking.
- Timber windows are rotten.
- External decoration is overdue with exposed timber.
- Damp and mould growth in the south/west store.
- Ceramic wall tiles are boss and missing in isolated areas.
- Sink base units are life expired and are collapsing.

#### 3.4 Mechanical and Electrical Installations

- The main oil boiler is life expired due to age and is in poor condition. There is no back up boiler for this installation.
- Heating system pipework is approaching the end of its useful life.
- Heating system pipework is uninsulated in areas.
- Steel panel radiators are reaching the end of their useful life.
- Heating system controls are life expired due to age and no BEMS is installed.
- Toilet rooms in the main school and kitchen block have no mechanical extract systems installed.
- Electrical point of use water in the staff room is approaching the end of its useful life.
- Hot and cold water distribution pipework is uninsulated in areas.
- A number of distribution boards in the main school are life expired due to age and contain fuses/fuse wire protective devices.
- Distribution boards in the canteen building are life expired due to age and contain fuses/ fuse wire protective devices.
- Main busbar and associated switchgear in the games' hall building is life expired due to age.
- General wiring in the main school building is life expired due to age.
- General wiring in the canteen building is life expired due to age.
- General wiring in the games' hall building is life expired due to age.
- Wiring accessories in the main school building are life expired due to age.
- Wiring accessories in the canteen building are life expired due to age.
- Wiring accessories in the games' hall building are life expired due to age.
- Some electrical convectors in the main school, canteen and games hall buildings are life expired due to age.
- The CCTV system is only a 1 camera field.
- There is no intruder alarm system installed in either of the buildings.

### 3.5 External Areas

- Tarmacadam (shared) access road is extensively potholed.
- Surface water drains are blocked.

## 4 Conclusion

## 4.1 A brief summary of the elements condition.

Element	Condition	Priority
Roofs	D	1
Floors & Stairs	С	3
Ceilings	С	3
Ext. Walls, Windows & Doors	D	2
Internal Walls & Doors	В	4
Sanitary Services	В	4
Mechanical	С	2
Electrical	С	2
Decoration	С	2
Fixed Int. Facilities	С	3
External Areas	В	4
Outdoor Sports Facilities	В	4

This information must be transferred to the Master Core Fact Sheet.

### 4.2 Improvements Recommended

To prevent or reduce, vandalism / damage / accelerated deterioration.

- Investigate maintenance responsibility of the private access road (potholed).
- Improve access to School roof space for essential maintenance ladder and walkways.
- Improve access from old roof space to north extension roof space.
- Provide access to the roof space above classroom 2 (room 1/14).
- Replace asbestos roof covering and guttering to the Games Hall (HORSA hut).
- Increase the field of CCTV.
- Install an intruder alarm system linked to a call centre.
- Install a BEMS.
- Replace the existing oil fired boiler with 2. (1 to act as back up)
- Replace the heating system pipework and heat emitters.
- Upgrade the heating system controls.
- Upgrade internal lighting to LED.
- Replace original electrical wiring and life expired switchgear.
- Replace life expired electric convector heaters.
- Insulate all uninsulated water distribution pipework.
- Install time controls on hot water tank immersion heaters to allow programmed switching off.

## Appendix A

#### **Limitations and Exclusions**

#### Introduction

We will not seek to impose any particular limitations upon the survey work beyond those of normal surveying practice.

We will carry out a detailed, non-disruptive, visual inspection of the exposed parts of the building fabric that are readily and safely accessible at the time of our survey, using our standard survey equipment.

Our report will express our opinion on the condition and standard of construction of the inspected parts of the property and recommend further investigation or repair where necessary.

The survey will be limited to the subject property and no responsibility will be accepted for any defects that might materially affect the property, which are out with the scope of the survey.

#### **Health and Safety**

The inspection will be executed in a fashion in compliance with the Health & Safety at Work, etc Act 1974. Unless otherwise stated, it will be done without the benefit of internal or external scaffolding, guard rails or mechanical hoists. The external inspection will, therefore, be limited to ground level to inspection from accessible opening in the external fabric, or by the use of a 5 metre sectional ladder.

#### **Deleterious Materials**

Testing of components or taking of samples will not be taken through our inspection. If the presence of deleterious materials is suspected in the construction of the building, we will recommend further investigations are carried out by the appropriate specialists. Our inspection does not constitute an asbestos survey in accordance with the Control of Asbestos at Work Regulations.

### **Services**

We will carry out a visual inspection of the primary service installations to include electrical and mechanical services where accessible. No tests of existing services will be undertaken at the time of our inspection. If, as a result of inspection and where considered necessary, we will advise if further investigations and reports should be obtained by independent specialists.

Unless agreed beforehand, our inspection will not comment on the suitability of the property for any use and the client is, therefore, advised to ensure that their use is possible and all processes, trades and activities are viable and permitted. No enquiries will be made to any local or statutory authority regarding any form of "Notice" that might have been served on the property at any time in the past or present. Similarly our report excludes any investigation into the structural design and suitability and compliance with legislation relating to buildings.

#### **Environmental Conditions**

The scope of the survey will be limited by the particular weather conditions pertaining at the time of inspection and no guarantee will be given with regard to the performance of the elements of the building during different conditions.

Where existing, the external inspections will be limited by the presence of any coverings of vegetation and no stripping off of the vegetation, including ivy, trellises, etc will be undertaken.

#### **Contamination and Pollution**

We will not make enquiries or investigations as to whether the property or any part of it or any neighbouring property appears on any register of contaminated land or might be contaminated or otherwise affected within the scope of the Environmental Protection Act 1990 or other legislation. We will, therefore, be unable to report that the property is free from risk in this respect. For the purpose of our report we will assume that such enquiries would reveal nothing which would affect the terms of our report.

#### Confidentiality and Use.

Our report is for the sole use of Moray Council and is confidential to the Council and their Professional Advisors. It should not be reproduced in whole or in part or relied upon by a Third Party for any purpose without the express prior written consent of Moray Council.

It should be understood that the report must not be used as any form of specification. Prior to the selection of an appropriate specification, it is likely that further investigation and exploratory works will be required following on from the survey in order to determine the full extent of the specification works necessary prior to submission to contractors for pricing.

# Appendix B

# **Record Photographs**

# Roofs



1. Overview of school site



2. School building - timber trusses



3. Timber sarking boards



4. Access to north wing



5. Games Hall roof structure



6. Dining Hall roof structure





7. School building - natural slate

8.





9. 10. Recently replaced clay ridge tiles



11. Metal sheet "Decra" to north wing



12. Minor surface erosion



13. GRP to flat roof, blistered and uneven



14.



15. Corrugated asbestos to Games Hall



16. Extensive moss coverage



17. Damaged asbestos roof sheets



18. Felt roof to Dining Hall



19. Felt to shallow pitch



20. Evidence of previous repairs



21.



22. Collapsing plywood soffit to Dining Hall



23.



24. Minimal mineral fibre insulation to School building



25. Cast iron gutters to school building



26. Sagging cast iron gutters



27. Part blocked asbestos gutters



28.



29. Leaking gutters



30. Cast iron gutters to Dining Hall



31. Cast iron gutters part blocked



32. Rainwater gullies, part blocked



33.



34. Cast iron hopper heads and downpipes to school building



35. Cast iron downpipes



36.



37. Surface corrosion



38. UPVC downpipes to Games Hall



39. Cast iron downpipes to Dining Hall



40. Cast iron SVP's to school building



41. Cast iron SVP to Games Hall




42. Stone chimney






43. 44. Boiler house chimney







46. Two uncapped chimney pots

# **External Walls**



47. Stone walls to school building



48.





49. Eroded, crumbling skew stones

50.





51. 52. Concrete framed walls to Games Hall



53. Isolated cracking to concrete frame



54. Underfloor ventilation to the school building



55. Underfloor ventilation to the school building



56. Floor level to Games Hall



57. Floor level to Dining Hall



58. Underfloor ventilation to Dining Hall



59. Pointing to stonework



60. Painted textured render to entrance and toilets



61. Roughcast to north wing



62. Isolated cracking to textured render



63.



64. Painted roughcast to Games Hall



65. Timber linings to Dining Hall



66.



67. Timber double doors to school entrance



68. Timber fire exit door - school



69. Timber double doors to Games Hall



70. Timber single door to Games Hall



71. Timber double doors to Dining Hall



72. Timber single door to Dining Hall



73. Timber fire exit door – Dining Hall



74. Small aluminium windows



75. Medium aluminium windows



76. Large aluminium windows



77. Large windows internally



78. PVC window in school reception





79.

80. Small metal windows to Games Hall



81. Medium metal windows to Games Hall



82. PVC windows to Dining Hall



83. Small timber windows to Dining Hall



84. Rot in timber windows



85. Large timber windows



86. Rot in timber windows



87. Timber windows internally



88. Double glazing to aluminium windows



89. Double glazing to PVC windows



90. Single glazing to timber windows





91. Broken glazing to Games Hall, below internal linings

92.



93. Typical lever handle

# **External Decoration**





94. Timber fascia boards - school

95.



96. Timber fascia – Dining Hall



97. Timber soffit – Dining Hall



98. Cast iron rainwater goods



99. Timber windows



100. 101. Timber doors



# **Steps and Ramps**



102. Concrete step - school



103. Concrete steps – Games Hall



104. Concrete steps – Dining Hall



105. Concrete ramp – Games Hall



106. Galvanised guard rail - Games Hall

## **Floors**



107. Suspended timber floors



108. School - Carpet worn



109. School - Carpet soiled



110. School – Sheet vinyl



111. School - Damaged vinyl



112. School – Vinyl lifting



113. School – Quarry tile to Boys Toilet



114. Painted concrete floor to Boiler House



115. Games Hall – Vinyl tile



116. Games Hall - Linoleum



117. Dining Hall - Carpet



118. Dining Hall – sheet vinyl



119. Dining Hall – Quarry tile to Kitchen



120. Dining Hall – Timber boards to dining hall



121.




122. Concrete stairs to basement



123. Damaged concrete nosings

# <u>Ceilings</u>







125.



126.





128. Plaster and plasterboard ceilings



129. Timber boarded ceiling



130. Games Hall – Plasterboard ceilings



131. Dining Hall – Fibreboard ceilings



132.

# **Internal Walls**



133. School – Stone and concrete block walls



134. Games Hall - Brickwork walls



135. Dining Hall – Timber stud partitions



136. School – Lath & plaster wall finish



137. School - plastered walls



138. School - Plasterboard walls



139.



140. School – Timber linings at low level



141. School – Ceramic tiled splashbacks



142.



143. Games Hall - Plasterboard walls



144. Dining Hall – Fibreboard walls



145. Dining Hall – Boss ceramic tiles



146. Dining Hall - Loose and missing ceramic tiles



147. School – Timber hallow core doors



148. Some with vision panels



149. School – Timber double doors



150. School – Timber panelled door



151. School – Timber double doors



152. School – Toilet cubical doors



153. School – Timber veneered doors



154. Games Hall - Timber hallow core door



155. Games Hall – Timber panelled door



156. Dining Hall – Timber hallow core doors



157. Dining Hall – Timber solid core double doors



158. Dining Hall – Veneered single doors



159. Dining Hall – Veneered double doors



160. Georgian wired glazing to doors



161. Typical lever handles



162. Aluminium push bar



163. Rim locks and brass knobs



164. Rim locks and Bakelite knobs

# Sanitary Ware



165. Stainless steel trough urinal



166. Stainless steel cistern



167. Typical pupil toilets



168.



169.



170. China vanity basins – pupil toilets



171. Wall hung basins - Staff & Dining Hall



172. Hairline cracks in basins



173. PVC waste pipes



174. Accessible toilet - School



175. Vanity units in pupil toilets



176. Commercial kitchen





177.

178. Stainless steel kitchen sinks






179.

180. Stainless steel inset basin







182. PVC waste pipes

## **Internal Decoration**



183. Painted ceilings



184. Concrete frame in the Games Hall



185. Painted walls



186.



187. Painted brickwork



188. Timber skirtings and joinery items

# <u>Furniture</u>



189. Classroom tables and chairs



190. Kitchen base units



191.





193. Staff room furniture



194.

### Mechanical and Electrical Photographs



195. Oil boiler - basement 0/33.



196. Oil storage/supply tank. External.



197. Heating control panel – basement 0/33.



198. Heating feed and expansion tank – attic space.



199. Heating pipework – basement 0/33



200. Heating pipework – attic space.



201. Radiator - main school classroom.



202. Radiator - school staff toilet.



203. Electric fan convector – games hall.



204. Electric convector canteen library room.



205. Electric radiant panels. Canteen block classroom.



206. Electric halogen heaters – games hall.



207. Hot water storage cylinder – kitchen.



208. Hot water storage cylinder – basement.



209. Point of use water heater - classroom 1/9



210. Point of use water heater – playgroup 1/22



211. Point of use water heater – staff room 1/13



212. Pipework – hot water girls toilets 1/4



213. Pipework – cold mains girls toilets 1/4



214. Pipework – cold mains staff toilets 1/2



215. Extract fan – main kitchen.



216. Extract fan - main kitchen roof.



217. Extract fans – heat recovery type. Games hall. 218. Supply fan system – basement 0/33





219. Switchgear – DBs and busbar/isolators – games hall store 1/30



220. Switchgear - 1/8 office cupboard



221. DB - example. 1/8 reception office cupboard



222. Switchgear – canteen block 1/15 cupboard.



223. General wiring out of DBs – games hall. 1/30 store.



224. General wiring from DBs 1/8 office cupboard.



225. Switch - lighting. Girls toilets 1/4



226. Switches and sockets playgroup 1/22



227. Lighting – boys toilets 1/6




228. Lighting – playgroup 1/22



229. Lighting – games hall.



230. Lighting – canteen block library.



231. Lighting class store 1/23



232. Lighting – access toilet 1/3



233. External lighting – canteen block.



234. External lighting – main school.



235. Emergency lighting class 1/14



236. Emergency exit lighting games hall.



237. Fire alarm system control panel main school.



238. Smoke detector main school 0/33



239. Smoke detector (wireless) canteen block library.



240. Fire alarm call point main school 1/1 entrance.



241. Fire alarm system radio link hub. Canteen block.



242. Fire alarm system radio signal transmitters - canteen block.



243. Disabled toilet alarm system access WC 1/3



244. Paxton NET2 door entry system – main school.



245. Period bell system - main school.



246. Hearing induction loop system – 1/8 office.



247. CCTV fixed camera main school main entrance.



248. CCTV DVR and monitor 1/8 office reception.

### **External Works**



249. Shared tarmacadam access road



250. Significant potholes



251. Tarmacadam access to car park



252. Tarmacadam car park



253. Isolated cracking and surface erosion



254. Tarmacadam playground to the rear



255. Cracked and damaged surface



256. Tarmacadam speed hump



257. Concrete footpath to Games Hall



258. Paving slab footpath to rear of Games Hall



259. Cracked and uneven paving slabs



260. Tarmacadam footpath to Dining Hall



261. Gravel footpath to rear of Dining Hall



262. Paving slab apron to long jump runway



263. Security mesh fencing



264. Concrete post and wire mesh fencing



265. Isolated erosion of concrete posts



266. Timber post and wire mesh fencing



267. Tubular rail separation to rear of school



268. Timber boarded fence to garden area



269. Security mesh single gates



270. Security mesh vehicle gates



271. Natural stone walls to the perimeter of the school



272. Isolated repointing required to stabilise the masonry





273. School signage

274.



275. Surface water road gully drainage



276. Timber external store



277. Rotten windows



278. Rotten door



279. Pupil shelter



280. Galvanised cycle hoops



281. Timber shed – Long jump



282. Timber shed – by Dining Hall



283. Oil tank enclosure



284. Galvanised framed polytunnel



285. Timber utility poles



286. Landscaping – grass and trees



287. Grass sports field



288.