

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)	Area: Forres
Plot Number: 5.40	Feature Id - Location: Proludic Surf Slide
Feature Type: Play Equipment Item	Contract Area: Grounds Maintenance

Batch: 178922 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.09/22.02/23.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 178164 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.09/22.02/23.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 177393 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.09/22.02/23.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 176081 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.09/22.02/23.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 175605 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.09/22.02/23.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 172960 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.09/22.02/23.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 164516 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.09/22.02/23.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.40

Feature Id - Location: Proludic Surf Slide

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 158581 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19. 07/21 08/21.09/22.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 157374 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19. 07/21 08/21.09/22.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 152576 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19. 07/21 08/21.09/22.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 149095 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19. 07/21 08/21.09/22.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 145106 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 30/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19. 07/21 08/21.09/22.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143821 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19. 07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143071 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19. 07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.40

Feature Id - Location: Proludic Surf Slide

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 142381 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 141346 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 140556 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139598 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139209 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 137913 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 137745 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/12/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/09/2021 to 01/09/2023
Site: Alves Primary School - Alves (ALVEALPRSC)
Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.40

Feature Id - Location: Proludic Surf Slide

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 136872 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 28/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135921 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135316 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Top panels rotted, need replaced.3.10.19.07/21 08/21.
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC) Area: Forres
 Plot Number: 5.50 Feature Id - Location: Proludic Pony Springer
 Feature Type: Play Equipment Item Contract Area: Grounds Maintenance

Batch: 178927 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 03/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 178163 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 06/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 177392 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 08/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 176082 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 175604 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 04/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.50

Feature Id - Location: Proludic Pony Springer

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 172959 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 164515 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 158580 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 157373 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 152611 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC) Area: Forres
 Plot Number: 5.50 Feature Id - Location: Proludic Pony Springer
 Feature Type: Play Equipment Item Contract Area: Grounds Maintenance

Batch: 149101 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 06/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 145105 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 30/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143822 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 04/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143070 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 07/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 142382 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.50

Feature Id - Location: Proludic Pony Springer

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 141347 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 140555 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139604 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139215 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 137914 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.50

Feature Id - Location: Proludic Pony Springer

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 137744 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/12/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 136878 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 28/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135922 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135315 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Seat gone, new seat needed 5.9.19 .Seat needs replacing , coming away from unit.8.8.19.11/19 01/20.. Seat missing, replacement needed.02/20. Seat awaiting replacement. 03/20.Seat missing to be replaced shortly.06/20.seat replaced, 06/20.
Paintwork Condition	PAIN	Poor	7.5000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.51

Feature Id - Location: Sutcliffe Dish Roundabout

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 178928 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 178161 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 177390 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 176083 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 175602 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 172957 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 164513 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 158578 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC) Area: Forres
 Plot Number: 5.51 Feature Id - Location: Sutcliffe Dish Roundabout
 Feature Type: Play Equipment Item Contract Area: Grounds Maintenance

Batch: 157372 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 08/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 152613 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 03/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 149099 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 06/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 145103 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 30/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143823 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 04/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143068 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 07/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 142384 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 141349 - Inspection Batch

Route: Playground Inspection Officer: Playground Fitter Date: 05/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.51

Feature Id - Location: Sutcliffe Dish Roundabout

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 140553 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139602 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139213 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 137916 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 137742 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/12/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 136876 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 28/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135924 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135313 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.52

Feature Id - Location: Sutcliffe Nest Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 178925 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 178160 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 177389 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 176084 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 175601 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 172956 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 164512 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 158577 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.52

Feature Id - Location: Sutcliffe Nest Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 157371 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 152616 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 149098 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 145102 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 30/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143824 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 143067 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 142385 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 141350 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.52

Feature Id - Location: Sutcliffe Nest Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 140552 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139601 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 139212 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 137917 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 137741 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/12/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 136875 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 28/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135927 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Batch: 135312 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.53

Feature Id - Location: Donkey Spring Animal - Sutcliffe

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 178924 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 178159 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 177388 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 176085 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 175600 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 172955 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 164511 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 158576 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.53

Feature Id - Location: Donkey Spring Animal - Sutcliffe

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 157370 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 152615 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 149097 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 145101 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 30/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 143827 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 143066 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 142386 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 141351 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.53

Feature Id - Location: Donkey Spring Animal - Sutcliffe

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 140551 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 139600 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 139211 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 137918 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 137740 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/12/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 136874 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 28/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 135926 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 135311 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.54

Feature Id - Location: Rota Play - Wicksteed

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 178923 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 178158 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 177387 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 176086 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 175599 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 172954 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 164510 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 158575 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)		Area: Forres	
Plot Number: 5.54		Feature Id - Location: Rota Play - Wicksteed	
Feature Type: Play Equipment Item		Contract Area: Grounds Maintenance	
Batch: 157369 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 08/12/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000
Batch: 152614 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 03/11/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000
Batch: 149096 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 06/10/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000
Batch: 145100 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 30/08/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000
Batch: 143826 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 04/08/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000
Batch: 143065 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 07/07/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000
Batch: 142387 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 13/06/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000
Batch: 141352 - Inspection Batch			
Route: Playground Inspection		Officer: Playground Fitter	Date: 05/05/2022
Observation Type	Code	Grade	Score Notes
Overall Condition	G001	Good	2.5000 Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000
Playground Equipment Stability	P001	Good	2.5000

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 5.54

Feature Id - Location: Rota Play - Wicksteed

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 140550 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 139599 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 139210 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 137919 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 137739 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/12/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 136873 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 28/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 135925 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 135310 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bark gone, log surround deteriorating. 03/20
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 30.00

Feature Id - Location: Woodchip Safety Surface

Feature Type: Play Equip Safety Surface

Contract Area: Grounds Maintenance

Batch: 178926 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 178162 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 177391 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 176087 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 175603 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 30.00

Feature Id - Location: Woodchip Safety Surface

Feature Type: Play Equip Safety Surface

Contract Area: Grounds Maintenance

Batch: 172958 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 164514 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 158579 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 157368 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 152612 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 30.00

Feature Id - Location: Woodchip Safety Surface

Feature Type: Play Equip Safety Surface

Contract Area: Grounds Maintenance

Batch: 149100 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 145104 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 30/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 143825 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 143069 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 142383 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC)

Area: Forres

Plot Number: 30.00

Feature Id - Location: Woodchip Safety Surface

Feature Type: Play Equip Safety Surface

Contract Area: Grounds Maintenance

Batch: 141348 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 140554 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 139603 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 139214 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 137915 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Officer: Playground Fitter (PLAY)
 Route: Playground Inspection (P011)
 Inspected: 01/09/2021 to 01/09/2023
 Site: Alves Primary School - Alves (ALVEALPRSC)
 Report Type: Assessment

Site: Alves Primary School - Alves (ALVEALPRSC) Area: Forres
 Plot Number: 30.00 Feature Id - Location: Woodchip Safety Surface
 Feature Type: Play Equip Safety Surface Contract Area: Grounds Maintenance

Batch: 137743 - Inspection Batch
 Route: Playground Inspection Officer: Playground Fitter Date: 01/12/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 136877 - Inspection Batch
 Route: Playground Inspection Officer: Playground Fitter Date: 28/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 135923 - Inspection Batch
 Route: Playground Inspection Officer: Playground Fitter Date: 29/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.

Batch: 135314 - Inspection Batch
 Route: Playground Inspection Officer: Playground Fitter Date: 02/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Bark next to nonexistent nedds top up or matted. 3.10.19. Wood surround breaking down, 5.9.19 . Could do with being grass matting. Poor, bark very low. 8.8.19. Bark low, top up needed., timber surround missing, replacement needed. Bark non existent, very boggy ,lots of surface water. 03/21. New edging and bark topped up.07/21.