

School	Date of Last Re-inspection	Outcome/ Works required following inspection	Known Asbestos Present		
			Chrysotile (white)	Amosite (brown)	Crocidolite (blue)
ALVES PRIMARY SCHOOL	10/01/2023	no remedial works required	y	y	P
ANDERSONS PRIMARY SCHOOL	31/01/2023	no remedial works required	y	0	0
APPLEGROVE PRIMARY SCHOOL	MVPW (see note 1)		y	0	0
BISHOPMILL PRIMARY SCHOOL	25/08/2022	no remedial works required	y	y	P
BUCKIE HIGH SCHOOL	23/08/2023	encapsulation to tank room ceiling , floor tile removal from staff shower room - pending	y	y	0
BURGHEAD PRIMARY SCHOOL	28/06/2023	w/o to joiner - cupboard floor tiles covered over	y	y	P
CLUNY PRIMARY SCHOOL	16/11/2022	no remedial works required	y	y	0
CRAIGELLACHIE PRIMARY SCHOOL	05/09/2023	no remedial works required	y	0	0
CROSSROADS PRIMARY SCHOOL	MVPW (see notes 1+2)		y	0	0
CULLEN PRIMARY SCHOOL	23/08/2022	w/o to LARC - AC pipe removed from WC ceiling void & insulation jacket from boiler house	y	y	P
DALLAS PRIMARY SCHOOL	10/02/2023	no remedial works required	y	y	0
DYKE PRIMARY SCHOOL	20/10/2022	w/o to LARC - pipe wrap within boxing removed. Recommendation to remove AC roof - under review	y	0	0
EAST END PRIMARY SCHOOL	10/02/2023	no remedial works required	y	0	0
FINDOCHTY PRIMARY SCHOOL	01/09/2022	w/o to LARC - remedial works horsa hut roof. Recommendation to remove shed roofs - under review.	y	0	0
FORRES ACADEMY	28/02/2023	w/o to LARC - -encapsulation works & floor tile removal	y	y	0

GREENWARDS PRIMARY SCHOOL	15/03/2023	w/o to joiner - reattached non acm skirting to base of columns.	y	y	0
HOPEMAN PRIMARY SCHOOL	21/10/2022	w/o to roofer - slipped tiles to annexe building roof	y	0	P
HYTHEHILL PRIMARY SCHOOL	04/10/2022	no remedial works required	y	0	0
INVERAVON PRIMARY SCHOOL	MVPW (see note 2)		y	0	0
KEITH GRAMMAR SCHOOL	29/05/2023	w/o to LARC - to remove roof sheeting from bike shelter. Recommendation to remove shed roof - under review	y	y	y
KINLOSS PRIMARY SCHOOL	14/11/2022	no remedial works required	y	y	P
KNOCKANDO PRIMARY SCHOOL	11/05/2023	w/o to LARC - broken floor tiles to be lifted from entrance to horsa hut. Recommendation to remove Horsa hut roof - under review.	y	0	P
LOGIE PRIMARY SCHOOL	04/04/2023	w/o to LARC - encapsulation works store ceilings and external store	y	y	0
MILNES HIGH SCHOOL	13/04/2023	w/o to LARC - encapsulation works to soffits	y	0	P
MILNES PRIMARY SCHOOL	04/07/2022	no remedial works required	y	0	0
MOSSTODLOCH PRIMARY SCHOOL	23/03/2023	w/o to LARC - encapsulation works to textured coating to ceilings	y	y	0
MOSSTOWIE PRIMARY SCHOOL	10/02/2023	no remedial works required	y	0	0
NEW ELGIN PRIMARY SCHOOL	11/10/2022	w/o to LARC -. encapsulation of packers in ceiling void,	y	y	0
NEWMILL PRIMARY SCHOOL	05/09/2023	no remedial works required	y	0	0
PILMUIR PRIMARY SCHOOL	02/06/2023	w/o to LARC - encapsulation works to textured coating to ceilings	y	0	0
PORTESSIE PRIMARY SCHOOL	12/10/2022	no remedial works required	y	y	y

PORTGORDON PRIMARY SCHOOL	17/11/2022	no remedial works required	y	y	0
PORTKNOCKIE PRIMARY SCHOOL	23/08/2022	no remedial works required	y	0	0
ROTHES PRIMARY SCHOOL	30/03/2023	Recommendation to remove AC roofs to outbuildings - under review	y	0	0
SEAFIELD PRIMARY SCHOOL	04/09/2023	w/o to LARC - encapsulation to skylight putty	y	y	0
SPEYSIDE HIGH SCHOOL	06/07/2023	no remedial works required	y	y	P
ST GERARDINE PRIMARY SCHOOL	MVPW (see note 1)		y	0	0
ST PETERS PRIMARY SCHOOL	12/10/2022	w/o to LARC - floor tile removal	y	0	0
ST THOMAS PRIMARY SCHOOL	13/10/2022	no remedial works required	y	y	0
TOMINTOUL PRIMARY SCHOOL	05/09/2023	bitumen adhesive sampled. Damage to non ACM floor tiles in electrical store - to be removed pending analysis results	y	0	0
WEST END PRIMARY SCHOOL	04/09/2023	no remedial works required	y	y	0
			41	20	2 (known)

All re-inspections to assess the current condition of ACMs are carried out in-house (by Moray Council's asbestos officer). All remedial works involving ACMs carried out by LARC - Licensed asbestos removal contractor

MVPW - managed via planned works (not on current reinspection list)

note 1- ACMs are concealed below floor coverings and therefore not visible for inspection, e.g. Bitumen residues below fitted vinyl or floor screed

note 2 - school is mothballed and has only low risk materials present (e.g. floor tiles)

P - Asbestos type Presumed - where a material is suspected as having asbestos content but cannot be sampled due to safety or accessibility issues (such as live electrics) and, there is insufficient evidence (associated sampling or manufacturer's confirmation) to confirm if/ which the type of asbestos has been used in the product, the default asbestos type 'Crocidolite' has been used. Further investigation to be obtained via R&D request prior to intrusive works

Y - Confirmed

0 - Not present