

Harbour Identified Improvement Works at March 2010

| | Description | Estimate |
|--|--|----------|
| Buckie | Handrail extensions to ladders | £39,750 |
| | No.2 Pier - Deck Replacement | £55,000 |
| | North Pier - Inner face of jetty concrete repair | £65,000 |
| | North West Pier - Inner face of basin 4 concrete repair at 2no locations | £60,000 |
| | North Pier outside face of parapet near rock armour - Reface | £52,500 |
| | Removal of timber jetty | £65,000 |
| | At rear of Harbour Office - Demolition of sheds | £27,500 |
| Burghead | South Pier - Cathodic protection | £103,150 |
| | Spending Beach - Reinststate rip rap protection | £45,000 |
| | North Pier jetty - Concrete encasing of bearing piles | £82,500 |
| | South Pier - Reface in front of sheet piles | £525,000 |
| | North Pier - Cathodic protection | £65,675 |
| | Handrail extensions to ladders | £14,250 |
| | Middle Pier - Toe rails | £30,000 |
| | Boatyard - Dyke construction | £5,500 |
| | Boatyard - Rip rap protection | £22,500 |
| | Middle Pier - Remove rock outcrops at slipway | £4,000 |
| | North Pier - Replace decking opposite south pier | £11,000 |
| Replace red and green navigation lights | £10,000 | |
| Cullen | Seatown corner - Reface at piles | £32,500 |
| | Handrail extensions to ladders | £7,500 |
| | Pontoons - Replace chains with piles | £65,000 |
| | Middle Pier - Replace toe rails | £34,125 |
| Findochty | Pontoons - Install 4no. additional fingers | £20,000 |
| | Install security gates at 3no. Pontoons | £7,500 |
| | Provide water supply to middle pontoon | £4,500 |
| | Pontoons - Replace pontoon fixing chains with piles | £300,000 |
| | Handrail extensions to ladders | £15,375 |
| | At Slipway - Improve Lighting | £1,000 |
| | Add timber fender to east berth of west pontoon | £2,000 |
| | West Pier - Cathodic protection to sheet piles | £31,450 |
| | Pontoons - Replace all 3 sets of guide rails | £12,000 |
| East Pier - Cathodic protection to sheet piles | £12,025 | |
| Pontoons – Replace existing | £500,000 | |
| Hopeman | South Pier - Inner face refacing | £152,625 |
| | West Pier - Toe rails | £45,000 |
| | East Pier - Toe rails | £30,000 |
| | Middle Pier - Toe rails | £60,000 |
| | Handrail extensions to ladders | £20,250 |
| | South Pier - Replace railing | £2,750 |
| | Middle Pier pierhead - Reface (Ph3) | £16,500 |
| East Pier - Replace red leading lights | £6,000 | |

| | | |
|-------------|--|-------------------|
| | South Pier Steps - Install railing at steps | £2,250 |
| | Middle Pier NW corner - Reface (Ph2) | £16,500 |
| Portknockie | Entrance Jetty at head of jetty - Concrete repair and reface | £55,000 |
| | Middle Pier - Replace pontoon fixing chains with piles | £125,000 |
| | North Pier - Inner face concrete works below MLWS | £150,000 |
| | North Pier - At pontoons reface over 20m | £80,000 |
| | Breakwater - Concrete repairs at head of pier | £45,000 |
| | Handrail extensions to ladders | £10,500 |
| | MacDonald Pier - New slipway | £40,000 |
| | Inner Basin - Replace road culverts | £7,500 |
| | North Pier - Replace pontoon guide rails | £12,000 |
| | Middle Pier - Ladder replacement | £7,500 |
| | North Pier - Ladder replacement | £4,000 |
| | Slipway - Protect bank from erosion south of slipway | £7,500 |
| | Total identified in reserve list | £3,224,175 |