

RPII ANNUAL PLAYGROUND INSPECTION REPORT



ALVES PRIMARY SCHOOL MORAY COUNCIL 5th June 2021

This inspection was carried out by James Busby RPII Signed

ltem No.	Item Description	Inclusive Y/N	Quality Score	Compliance with BSEN 1176 Y/N	Risk Assessment	Actions	Item Priority	Safety Surface Compliance to BSEN 1177	Surfacing Risk Assessment	Actions	Surface Priority Works
1	Item Basket Swing Manufacturer: Sutcliffe Label: Yes Age Range: 2 – 12 Life Expectancy: 10 Years Surfacing: Woodchip	Y	10	Y	L	N/A	5	Y	L	N/A	5
2	Item Overhead Rotator Manufacturer: Wicksteed Label: Yes 2009 Age Range: 8 – 12 Life Expectancy: 12 Years Surfacing: Woodchip	Ν	10	Y	L	N/A	5	Y	L	N/A	5
Overa	II Mean Score =	1	-		·						

	*	Ρ	ric	ority	Action
--	---	---	-----	-------	--------

*Quality Score

Poor = 2

- 1 Action Immediately (Contact Client) Good = 10Fair = 5
- 2 Action within 1 month
- 3 Action within 3 months
- 4 Action within 9 months
- 5 Monitor

N.B. Mean Score = total quality score divided by the number of items.

*Risk Assessment 1 to 20 (Probability x Severity)

Probability	Severity	Risk Level
1 – Highly Unlikely	1 – Very Minor	1 - 5 Low
2 – Unlikely	2 – Minor	6 - 11 Medium
3 – Likely	3 – Major	12 - 20 High
4 – Higher Likely	4 – Very Major	
- •	5 – Catastrophic	

Site Name: Alves Primary School, 3 Main Road, Alves, Elgin, IV30 8UR

ltem No.	Item Description	Inclusive Y/N	Quality Score	Compliance with BSEN 1176 Y/N	Risk Assessment	Acti	ons	Item Priority	Safety Surface Compliance to BSEN 1177	Surfacing Risk Assessment	Actions	Surface Priority Works
3	Item Donkey Rocker Manufacturer: Wicksteed Label: Yes Age Range: 2 - 6 Life Expectancy: 10 Years Surfacing: Woodchip	Ζ	5	Ν	L	0	Falling space overlaps free space of roundabout.	4	Y	L	N/A	5
4	Item Dish Roundabout Manufacturer: Wicksteed Label: Yes 2009 Age Range: 4 – 12 Life Expectancy: 12 Years Surfacing: Woodchip	Y	5	Ν	L	0	Item too close to donkey rocker by 50mm.	4	Y	L	N/A	5
Overa	II Mean Score =		-				I	1				

* Priority Action	*Quality Score	N.B. Mean Score = total quality	*Risk Assessment 1 to 20 (Probability x Severity)				
 Action Immediately (Contact Client) Action within 1 month Action within 3 months Action within 9 months Monitor 	Good = 10 Fair = 5 Poor = 2	score divided by the number of items.	Probability 1 – Highly Unlikely 2 – Unlikely 3 – Likely 4 – Higher Likely	Severity 1 – Very Minor 2 – Minor 3 – Major 4 – Very Major 5 – Catastrophic	Risk Level 1 - 5 Low 6 - 11 Medium 12 - 20 High		

ltem No.	Item Description	Inclusive Y/N	Quality Score	Compliance with BSEN 1176 Y/N	Risk Assessment	Actions	Item Priority	Safety Surface Compliance to BSEN 1177	Surfacing Risk Assessment	Actions	Surface Priority Works
5	Item Stand Alone Slide Manufacturer: Proludic Label: Yes Age Range: 4 – 8 Life Expectancy: 10 Years Surfacing: Woodchip	Ν	5	Ν	М	Replace rotting slide sides at slide entrance. Monitor rot in slide sides.	2	Y	L	N/A	5
6	Item Horse Rocker Manufacturer: Proludic Label: Yes 2009 Age Range: 2 – 6 Life Expectancy: 12 Years Surfacing: Safa Grass Mats	Ν	10	Y	L	N/A	5	Y	L	N/A	5
Overa	II Mean Score =	1	7.5				1				

*Quality Score

Poor = 2

- 1 Action Immediately (Contact Client) Good = 10Fair = 5
- 2 Action within 1 month
- 3 Action within 3 months
- 4 Action within 9 months
- 5 Monitor

N.B. Mean Score = total quality score divided by the number of items.

*Risk Assessment 1 to 20 (Probability x Severity)

Probability	Severity	Risk Level
1 – Highly Unlikely	1 – Very Minor	1 - 5 Low
2 – Unlikely	2 – Minor	6 - 11 Medium
3 – Likely	3 – Major	12 - 20 High
4 – Higher Likely	4 – Very Major	
	5 – Catastrophic	

Site Name: Alves Primary School, 3 Main Road, Alves, Elgin, IV30 8UR

<u>TYPE</u>	GENERAL QUALITY COND	DITION	ACTIONS	<u>RISK</u> ASSESSMENT	PRIORTY
Boundary Fencing	5		5 Repair mesh.		3
NO SIGNAGE Signs	2		Signage recommended with play area rules of play and an emergency contact number.	L	3
Paths/Surfacing	10		N/A	L	3
	OVERALL MEAN SCORE:	5.7			

ANCILLARY STRUCTURES

* Priority Action	*Quality Score	N.B. Mean Score = total quality	*Risk Assessment 1	to 20 (Probability x	severity)
 Action Immediately (Contact Client) Action within 1 month Action within 3 months Action within 9 months Monitor 	Good = 10 Fair = 5 Poor = 2	score divided by the number of items.	Probability 1 – Highly Unlikely 2 – Unlikely 3 – Likely 4 – Higher Likely	Severity 1 – Very Minor 2 – Minor 3 – Major 4 – Very Major 5 – Catastrophic	Risk Level 1 - 5 Low 6 - 11 Medium 12 - 20 High