


Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in
Street Inspection History

Inspection Date	Survey Method	Defects
17/06/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
08/07/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
05/08/2025	Driven (Rural) / Walked (Urban)	
09/09/2025	Driven (Rural) / Walked (Urban)	
02/10/2025	Walked (Urban Inspections)	
05/11/2025	Driven (Rural) / Walked (Urban)	
03/12/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
08/01/2026	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
03/02/2026	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
03/03/2026	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
07/04/2026	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
05/05/2026	Driven (Rural) / Walked (Urban)	
09/06/2026	Driven (Rural) / Walked (Urban)	




Instruction Reference: M-0154028
Instruction Created: 17/06/2025 15:14:00
Instruction Status : **Works Complete**
Inspection: Safety Inspection Area W07 - 06 (Jun) on the 17th of June 2025
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 17/06/2025 15:14
Target Date: 29/07/2025 15:14
Completion Date: 30/06/2025 14:11
Location Description: From Mosstodloch: 160m after the Riding Centre access road, northbound side of the carriageway.
Description of Works: E&C Pothole - 459mm x 400mm x 35mm

Moray Council


Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0154030
Instruction Created: 17/06/2025 15:18:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 06 (Jun) on the 17th of June 2025
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 17/06/2025 15:18
Target Date: 29/07/2025 15:18
Completion Date: 30/06/2025 13:49
Location Description: From Mosstodloch: 350m after the Riding Centre access road, southbound side of the carriageway.
Description of Works: E&C Pothole and 2 Patches- 300mm x 200mm x 40mm, 1m x 300mm a d 600mm x 150mm




Instruction Reference: M-0154031
Instruction Created: 17/06/2025 15:23:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 06 (Jun) on the 17th of June 2025
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 17/06/2025 15:23
Target Date: 29/07/2025 15:23
Completion Date: 30/06/2025 13:49
Location Description: From Mosstodloch: 575m after the Riding Centre access road, northbound side of the carriageway.
Description of Works: E&C Pothole -500mm x 400mm x 35mm

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0154032
Instruction Created: 17/06/2025 15:27:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 06 (Jun) on the 17th of June 2025
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 17/06/2025 15:27
Target Date: 29/07/2025 15:27
Completion Date: 30/06/2025 13:45
Location Description: From Mosstodloch: 175m after the layby, at the double bend, northbound side of the carriageway.
Description of Works: E&C small Pothole



Instruction Reference: M-0154033
Instruction Created: 17/06/2025 15:30:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 06 (Jun) on the 17th of June 2025
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 17/06/2025 15:30
Target Date: 29/07/2025 15:30
Completion Date: 30/06/2025 13:33
Location Description: From Mosstodloch: 270m after the layby, both sides of the carriageway.
Description of Works: E&C 5 Patches - 1.1m x 400mm and 4 small Patches.



Instruction Reference: M-0154034
Instruction Created: 17/06/2025 15:44:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 06 (Jun) on the 17th of June 2025
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 17/06/2025 15:44
Target Date: 29/07/2025 15:44
Completion Date: 30/06/2025 13:24
Location Description: From Mosstodloch: 385m after Laughhill access rd, northbound side of the carriageway

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Description of Works: E&C 2 Potholes - 2 x 400mm x 300mm x 30mm and 2 Patches - 2m x 100mm and 250mm x 200mm

Instruction Reference: M-0154035
Instruction Created: 17/06/2025 15:48:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 06 (Jun) on the 17th of June 2025
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 17/06/2025 15:48
Target Date: 29/07/2025 15:48
Completion Date: 30/06/2025 13:17

Location Description: From Mosstodloch: 500m after the Laighhill access road, northbound side of the carriageway, on the outside of the white edge road marking.

Description of Works: E&C 2 edge Patches - 1m x 300mm x 60mm and 600mm x 300mm

Instruction Reference: M-0154643
Instruction Created: 08/07/2025 15:03:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 07 (Jul) on the 8th of July 2025
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 08/07/2025 15:03
Target Date: 19/08/2025 15:03
Completion Date: 11/07/2025 11:05

Location Description: From Garmouth: 200m after the 40mph/de-restriction signs, northbound side of the carriageway.

Description of Works: E&C Patch - 500mm x 500mm

Moray Council


Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Enquiry Reference: E-69046
Enquiry Created: 20/08/2025 15:49:15
Enquiry Status : *Investigation (In-Office)*
Item Type: Traffic Sign
Item Detail: Corroded Pole
Location Description: Just before layby on north bound approach to bends
Enquiry Comments: Pole is rusted through in places.



Instruction Reference: M-0155752
Instruction Created: 26/08/2025 15:11:00
Instruction Status : *Works Complete*
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 26/08/2025 15:11
Target Date: 07/10/2025 15:11
Completion Date: 05/09/2025 12:29
Location Description: From Mosstodloch:
365m after the Riding Centre access road - 65m x 500mm.
490m after the Riding Centre access road - 40m x 400mm.
670m after the Riding Centre access road - 20m x 400mm.
780m after the Riding Centre access road - 30m x 400mm.
Description of Works: Jetpatch the carriageway edge damage.

Marked

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026

Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0155755

Instruction Created: 26/08/2025 15:36:00

Instruction Status : *Works Complete*

Item Type: Carriageway

Item Detail: Carriageway Defects

Defect Category: P3 - 30 working days


Issued Date: 26/08/2025 15:36

Target Date: 07/10/2025 15:36

Completion Date: 05/09/2025 12:42

Location Description: From Mosstodloch: Between the parking place and Spey Cottage. Both sides of the carriageway and the centre at the double bend.

Description of Works: Jetpatch the carriageway damage - Approximately 90m. Marked



Instruction Reference: M-0156286

Instruction Created: 17/09/2025 15:31:00

Instruction Status : *Works Complete*

Item Type: Verge

Item Detail: Over-run damage

Defect Category: P3 - 30 working days

Issued Date: 17/09/2025 15:31

Target Date: 29/10/2025 15:31

Completion Date: 25/09/2025 12:39

Location Description: From Mosstodloch: Between the Riding Centre access and the double bends.

Description of Works: Pull the verge back, to the the edge of the carriageway, where required.



Instruction Reference: M-0157864

Instruction Created: 03/12/2025 14:49:00

Instruction Status : *Works Complete*

Inspection: Safety Inspection Area W07 - 12 (Dec) on the 3rd of December 2025

Item Type: Carriageway

Item Detail: Carriageway Defects

Defect Category: P3 - 30 working days

Issued Date: 03/12/2025 14:49

Target Date: 21/01/2026 14:49

Completion Date: 04/12/2025 11:12



Location Description: From Mosstodloch: 545m after the Riding Centre access, southbound side of the carriageway.

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Description of Works: E&C edge Patch - 1.5m x 500m, incorporating a 500mm x 300mm x 35mm edge pothole

Instruction Reference: M-0157865

Instruction Created: 03/12/2025 14:54:00

Instruction Status : *Works Complete*

Inspection: Safety Inspection Area W07 - 12 (Dec) on the 3rd of December 2025

Item Type: Carriageway

Item Detail: Carriageway Defects

Defect Category: P3 - 30 working days

Issued Date: 03/12/2025 14:54

Target Date: 21/01/2026 14:54

Completion Date: 04/12/2025 11:19

Location Description: From the Riding Centre access: Approximately 200m after the layby, southbound side of the carriageway.

Description of Works: E&C 4 edge Patches - 1m x 300mm, 700mm x 250mm, 400mm x 200mm and 1.1m x 300mm.

Instruction Reference: M-0157866

Instruction Created: 03/12/2025 14:59:00

Instruction Status : *Works Complete*

Inspection: Safety Inspection Area W07 - 12 (Dec) on the 3rd of December 2025

Item Type: Carriageway

Item Detail: Carriageway Defects

Defect Category: P3 - 30 working days

Issued Date: 03/12/2025 14:59

Target Date: 21/01/2026 14:59

Completion Date: 08/12/2025 13:28

Location Description: From Mosstodloch: 20m after the access to the wood, after the double bends, northbound side of the carriageway.

Description of Works: Bowl Fill the carriageway edge damage - 15m x 400mm. Approximately 1/2 ton - Marked.


Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026

Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0157867

Instruction Created: 03/12/2025 15:06:00

Instruction Status : *Works Complete*

Inspection: Safety Inspection Area W07 - 12 (Dec) on the 3rd of December 2025

Item Type: Carriageway

Item Detail: Carriageway Defects

Defect Category: P3 - 30 working days

Issued Date: 03/12/2025 15:06

Target Date: 21/01/2026 15:06

Completion Date: 04/12/2025 11:28

Location Description: From Mosstodloch: From the Drum Lodge access, for 30m, southbound side of the carriageway.

Description of Works: E&C 8 edge patches - 4m x 500mm, 3m x 500mm, 3 x 1m x 500mm, 3 x 500mm x 500mm,



Instruction Reference: M-0158243

Instruction Created: 19/12/2025 13:01:20

Instruction Status : *Works Complete*

Item Type: Bridge

Item Detail: All Bridge Enquiries

Defect Category: P2 - 5 Working Days

Issued Date: 19/12/2025 14:00

Target Date: 30/12/2025 14:00

Completion Date: 05/03/2026 17:58

Location Description:

Description of Works: Please order sign as per attached, should be at least A1 size and come with rails for attaching to posts. To be collected from Ashgrove Depot.



Instruction Reference: M-0158418

Instruction Created: 08/01/2026 14:36:00

Instruction Status : *Works Complete*

Inspection: Safety Inspection Area W07 - 01 (Jan) on the 8th of January 2026

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P2 - 5 Working Days

Issued Date: 08/01/2026 14:36

Target Date: 15/01/2026 14:36


Completion Date: 12/01/2026 09:56

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Location Description: From Mosstodloch: 480m after the Riding Centre access road, northbound side of the carriageway.

Description of Works: Cold Tar Pothole - 700mm x 400mm x 55mm

Instruction Reference: M-0158419

Instruction Created: 08/01/2026 15:20:00

Instruction Status : *Works Complete*

Inspection: Safety Inspection Area W07 - 01 (Jan) on the 8th of January 2026

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P2 - 5 Working Days

Issued Date: 08/01/2026 15:20

Target Date: 15/01/2026 15:20

Completion Date: 12/01/2026 10:01

Location Description: From Mosstodloch: 300m after the layby, opposite the access to the woods, southbound side of the carriageway.

Description of Works: Cold Tar Pothole - 600mm x 400mm x 40mm

Instruction Reference: M-0158873

Instruction Created: 23/01/2026 11:12:00

Instruction Status : *Works Complete*

Item Type: Carriageway

Item Detail: Carriageway Defects

Defect Category: P3 - 30 working days

Issued Date: 23/01/2026 11:12

Target Date: 06/03/2026 11:12

Completion Date: 26/01/2026 13:39

Location Description: From Garmouth: 500m after the 30mph/de-restriction signs, southbound side of the carriageway.


Description of Works: E&C patch - 5m x 400mm, incorporating a 500mm x 500mm x 40mm pothole

Moray Council


Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0159251
Instruction Created: 03/02/2026 11:02:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 02 (Feb) on the 3rd of February 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/02/2026 11:02
Target Date: 17/03/2026 11:02
Completion Date: 06/02/2026 11:49
Location Description: From Mosstodloch: 115m after the Riding Centre access road, northbound side of the carriageway and 1 patch on the opposite side of the carriageway.
Description of Works: E&C Pothole - 400mm x 300mm x 40mm and E&C 1 patch




Instruction Reference: M-0159252
Instruction Created: 03/02/2026 11:12:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 02 (Feb) on the 3rd of February 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/02/2026 11:12
Target Date: 17/03/2026 11:12
Completion Date: 04/02/2026 14:48
Location Description: From Mosstodloch: 415m after the Riding Centre access road, northbound side of the carriageway.
Description of Works: E&C 1 Pothole - 900mm x 250mm x 40mm and 1 edge patch - 1m x 400mm

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0159253
Instruction Created: 03/02/2026 11:16:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 02 (Feb) on the 3rd of February 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/02/2026 11:16
Target Date: 17/03/2026 11:16
Completion Date: 04/02/2026 14:41
Location Description: From Mosstodloch: 495m after the Riding Centre access road, northbound side of the carriageway.
Description of Works: E&C edge Pothole - 700mm x 300mm x 35mm




Instruction Reference: M-0159261
Instruction Created: 03/02/2026 11:54:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 02 (Feb) on the 3rd of February 2026
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 03/02/2026 11:54
Target Date: 17/03/2026 11:54
Completion Date: 04/02/2026 14:25
Location Description: From Garmouth: 45m after Spey Cottage, southbound side of the carriageway.
Description of Works: E&C 8 small Patches

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0160566
Instruction Created: 03/03/2026 14:57:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 14:57
Target Date: 15/04/2026 14:57
Completion Date: 09/03/2026 13:59
Location Description: From Mosstodloch: 35m after the Riding Centre access road, southbound side of the carriageway.
Description of Works: E&C 6 Patches - 3 x 500mm x 300mm. 3 x 300mm x 300mm




Instruction Reference: M-0160568
Instruction Created: 03/03/2026 15:04:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:04
Target Date: 15/04/2026 15:04
Completion Date: 09/03/2026 14:03
Location Description: From Mosstodloch: 370m after the Riding Centre access road, southbound side of the carriageway.
Description of Works: E&C Pothole - 500mm x 300mm

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0160569
Instruction Created: 03/03/2026 15:06:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:06
Target Date: 15/04/2026 15:06
Completion Date: 09/03/2026 14:08
Location Description: From Mosstodloch: 390m after the Riding Centre access road, southbound side of the carriageway.
Description of Works: E&C Pothole - 600mm x 350mm x 35mm




Instruction Reference: M-0160570
Instruction Created: 03/03/2026 15:08:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:08
Target Date: 15/04/2026 15:08
Completion Date: 09/03/2026 10:39
Location Description: From Mosstodloch: 420m after the Riding Centre access road, southbound side of the carriageway.
Description of Works: E&C Pothole - 1m x 300mm x 30mm and 2 small Patches.

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0160572
Instruction Created: 03/03/2026 15:11:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:11
Target Date: 15/04/2026 15:11
Completion Date: 09/03/2026 10:43
Location Description: From Mosstodloch: 575m after the Riding Centre access road, centre of the carriageway.
Description of Works: E&C Pothole - 500mm x 350mm x 40mm




Instruction Reference: M-0160573
Instruction Created: 03/03/2026 15:14:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:14
Target Date: 15/04/2026 15:14
Completion Date: 09/03/2026 10:51
Location Description: From Mosstodloch: 665m after the Riding Centre access road, southbound side of the carriageway.
Description of Works: E&C 2 edge Patches - 3m x 400mm and 500mm x 400mm.

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.


Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Instruction Reference: M-0160574
Instruction Created: 03/03/2026 15:21:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:21
Target Date: 15/04/2026 15:21
Completion Date: 09/03/2026 10:59
Location Description: From Mosstodloch: 100m after the layby, at the double bends, centre of the carriageway
Description of Works: E&C 2 Potholes - 2 x 400mm x 300mm x 35mm



Instruction Reference: M-0160575
Instruction Created: 03/03/2026 15:24:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Pothole
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:24
Target Date: 15/04/2026 15:24
Completion Date: 09/03/2026 11:00
Location Description: From Mosstodloch: 140m after the layby, northbound side of the carriageway
Description of Works: E&C a small Pothole



Instruction Reference: M-0160576
Instruction Created: 03/03/2026 15:31:00
Instruction Status : *Works Complete*
Inspection: Safety Inspection Area W07 - 03 (Mar) on the 3rd of March 2026
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 03/03/2026 15:31
Target Date: 15/04/2026 15:31
Completion Date: 09/03/2026 11:13
Location Description: From Mosstodloch: 200m after the Spey Cottage access road, southbound side of the carriageway.

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Description of Works: E&C the carriageway edge patches - totalling 15m x 400mm

Enquiry Reference: E-71432

Enquiry Created: 16/03/2026 14:11:00


Enquiry Status : *No Further Action*

Item Type: Carriageway

Item Detail: Miscellaneous

Location Description: Garmouth to Mosstodloch road at Essil Farm, IV32 7LE

Enquiry Comments: Call received 16/3/26 @ 14.04 - Customer has requested a call back regarding the roads maintenance works and shifting of laybys, he mentioned a layby being shifted near his property. Please can he be called back.



Instruction Reference: M-0161784

Instruction Created: 07/04/2026 13:15:00

Instruction Status : *Works Complete (Measure - Patching)*

Inspection: Safety Inspection Area W07 - 04 (Apr) on the 7th of April 2026

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P2 - 5 Working Days


Issued Date: 07/04/2026 13:15

Target Date: 14/04/2026 13:15

Completion Date: 09/04/2026 11:28

Location Description: From Mosstodloch: 640m after the Riding Centre access road, northbound side of the carriageway.

Description of Works: Cold Tar Pothole - 1m x 650mm x 60mm



Enquiry Reference: E-71618

Enquiry Created: 14/04/2026 08:54:00

Enquiry Status : *No Further Action*

Item Type: Carriageway

Item Detail: Carriageway Defects

Location Description: B9015 from Garmouth Road in Mosstodloch to South Road in Garmouth : About 1 mile north of Mosstodloch.

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 01/06/2025 To 30/06/2026
Street :- 26301301 - B9015 from Garmouth Road in Mosstodloch to South Road in



Enquiry Comments: email 06/04 09.32

Fault Details
Fault Area: Road Surface
Fault Type: Pothole
Subcategory Fault Type:
Further Fault Details: Large pothole on B9015 Mosstodloch to Garmouth. About 1 mile north of Mosstodloch, just before the double bend in the woods.

Instruction Reference: M-0163477
Instruction Created: 22/05/2026 16:20:00
Instruction Status : *Works Complete (Measure - Patching)*
Item Type: Carriageway
Item Detail: Carriageway Defects
Defect Category: P3 - 30 working days
Issued Date: 22/05/2026 16:20
Target Date: 03/07/2026 16:20
Completion Date: 25/05/2026 14:28
Location Description: From Mosstodloch: At the double bends, after the Riding Centre, northbound side of the carriageway
Description of Works: E&C Pothole - 350mm x 350mm x 35mm